

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
RECEIVED
South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Nabors Completion and Production Service Co. (Nabors)	Contact Les Teague
Address 5 miles West of Hobbs on Highway 180, Hobbs NM	Telephone No. 281 775-4201
Facility Name Hobbs Former Reclamation Plant	Facility Type: O&G Waste Management Facility permit No. NM-01-0022
Surface Owner State of New Mexico	Mineral Owner NA
API No. NA	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	3	19S	37E	1775	to the West	750	to the North	Lea

Latitude 32.694748 degrees Longitude 103.242135 degrees

NATURE OF RELEASE

Type of Release Hydrocarbon	Volume of Release Unknown	Volume Recovered Unknown
Source of Release Unknown	Date and Hour of Occurrence Unknown	Date and Hour of Discovery Unknown
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? SEE Describe Cause Below.	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Cause Unknown. During decommissioning of the tanks associated with the former reclamation plant area, stained soils were observed. Notification was provided to NMOCD. Mr. Leking was the NMOCD representative assigned to the case. Work plans and reports were presented to Mr. Leking. Affected soils have been excavated and disposed.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 50 feet by 60 feet and approximately one foot deep to the top of the cap rock. Soil sampling to delineate the affected soils has been completed. Analytical results and reports with path forward have been submitted to the NMOCD (Mr. Leking). Affected soil been excavated and been disposed off-site at a NMOCD permitted facility (R360 Permian basin, LLC). Confirmation samples collected show two areas above 100 mg/kg DRO). These areas have been treated with hydrocarbon degrading microbial solution.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *[Signature]*

Printed Name: Les Teague

Title: Senior Environmental Manager

E-mail Address: les.teague@Nabors.com

Date: 2014 10 13

Phone: 281 775 4201

Approved by Environmental Specialist:

Approval Date: 10-14-14

Expiration Date: 12-14-14

Conditions of Approval:

*Site samples upon
Rebate & reduce over area
NMOCD guide - Submit file
C-141 by 12-14-14*

Attached ☐

IRP-3380

* Attach Additional Sheets If Necessary

ogrid 295925

FT01428752020

NTO 1428752202

P70 1428752451

OCT 17 2014