

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OGD

OCT 14 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Form C-141  
Revised August 8, 2011

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Apache Corporation	Contact: Bruce Baker
Address: 2350 W Marland Blvd Hobbs, NM 88240	Telephone No. (432) 631-6982
Facility Name: WBDU 211	Facility Type: Oil Well
Surface Owner: Millard Deck Estates	Mineral Owner: _____
API No. 30-025-41875	

LOCATION OF RELEASE

Unit Letter A	Section 9	Township 21S	Range 37E	Feet from the 510'	North/South Line FNL	Feet from the 1310'	East/West Line FEL	County Lea
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	------------------------	-----------------------	---------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release: brine water	Volume of Release: 25 Barrels of brine water	Volume Recovered: Unknown
Source of Release: Frac Tank	Date and Hour of Occurrence: 9/2/2014 at 8:00 a.m.	Date and Hour of Discovery: 9/2/2014 at 8:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding (NMOCD)	
By Whom? Bruce Baker	Date and Hour: 9/3/2014 at 3:42 p.m. via email	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A contract transport driver was transferring fluid and overflowed the frac tank with brine water.

Describe Area Affected and Cleanup Action Taken.\*

The release was contained to the lease pad. The wet was removed by shovel and disposed of at an NMOCD approved facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker	Approved by Environmental Specialist: _____	
Title: Environmental Technician	Approval Date: 10-14-14	Expiration Date: 12-14-14
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval: <i>Site specific report Delinquent &amp; immediate area as per NMOCD guidelines. Submit Final C-141 by 12-14-14</i>	Attached <input type="checkbox"/> <i>12P-7381</i>
Date: 10/14/2014	Phone: (432) 631-6982	<i>09/10/873 H-101928828724 P-101928828921</i>

\* Attach Additional Sheets If Necessary

OCT 17 2014