

HOBBS OGD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

OCT 21 2014

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company DCP Midstream, LP	Contact Dan Landenberger
Address 10 Desta Drive, Suite 400 W, Midland, TX., 79705	Telephone# & E-mail: 432.620.4085/ drlandenberger@dcpmidstream.com
Facility Name Line Name: G Loop	Facility Type Pipeline

Surface Owner: Private	Mineral Owner	API No.
-------------------------------	---------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	6	22S	36E					Lea

Latitude N32.41985 Longitude W-103.30615

NATURE OF RELEASE

Type of Release: Gas and liquids (condensate)	Volume of Release unknown MCF; > 5 bbls condensate	Volume Recovered Unknown
Source of Release: G Loop Line	Date and Hour of Occurrence 10/20/14	Date and Hour of Discovery 10/20/14 2PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding	
By Whom? Dan Landenberger	Date and Hr. 10/20/14	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* **N/A**

Describe Cause of Problem and Remedial Action Taken.*

Line leak caused discharge of an unknown amount of natural gas and greater than 5 bbls of condensate onto the ground. Line has been shut in and will be depressurized prior to repair.

Describe Area Affected and Cleanup Action Taken.*

Affected area is approximately 20 feet by 50 feet. Any free liquids will be vacuumed up and contaminated soil excavated and removed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Dan Landenberger*

Approved by Environmental Specialist:

Printed Name: **Dan Landenberger**

Title: **Sr. Environmental Specialist**

Approval Date: **10-21-14**

Expiration Date: **12-21-14**

E-mail Address: **drlandenberger@dcpmidstream.com**

Conditions of Approval:

Attached

Date: **10/21/2014**

Phone: **432-620-4085**

*Site specific report
Delivered & reviewed over report
NMOCD grade. Submit final
C-141 by 12-21-14*

IRP-3389

ogrid 36785

10/14/2014 434811

10/14/2014 29440489

* Attach Additional Sheets If Necessary

OCT 27 2014