

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Prize 27 Federal #2 Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No. 30-025-31902 (nearest well)	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	27	22S	32E	660'	South	660'	East	Lea

Latitude N 32.35709° Longitude W 103.65617°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	1 bbl oil and 131 bbls produced water	Volume Recovered	130 bbls
Source of Release	Failure of the transfer pump overload button	Date and Hour of Occurrence	02/18/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jennifer Van Curen-BLM, Geoffrey Leking-OCD		
By Whom?	Kathy Purvis, BBC International	Date and Hour	02/18/2014 @ 3:33 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The failure of a transfer pump overload button caused 1 bbl of oil and 131 bbls of produced water to spill onto the ground. A total of 130 bbls of fluid were recovered via vacuum truck and the overload button was reset or replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area approximately 30' x 60' on location inside the containment. Remediation was completed in accordance with the remediation plan approved by Tomas Oberding of NMOCD via email on 08/11/2014 and approved by Jennifer Van Curen of the BLM in a meeting.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Chancey Summers			Approved by District Supervisor:	
Title:	HES Advisor			Approval Date:	10-23-14
E-mail Address:	Chancey.Summers@oxy.com			Expiration Date:	
Date:	10-10-14			Conditions of Approval:	
Phone:	(575) 397-8210			Attached	<input type="checkbox"/>

\* Attach Additional Sheets If Necessary

16698  
170 142 9 63 1664  
p 10 1429 63 1984

OCT 27 2014