

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1900 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Spencer Cluff
Address: 29 Vacuum Complex Lane	Telephone No. 575-391-3143
Facility Name: Ruby Federal Battery	Facility Type: Battery

Surface Owner: NMOCD	Mineral Owner NMOCD	API No. 3002520792
----------------------	---------------------	--------------------

LOCATION OF RELEASE

Unit Letter L	Section 17	Township 17S	Range 32E	Feet from the 1750	North/South Line South	Feet from the 990	East/West Line West	County LEA
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.8321781006055 Longitude - 103.794020703151

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 18.3 BBLS	Volume Recovered: 5 BBLS
Source of Release: water transfer pump	Date and Hour of Occurrence 03/10/14 7:30 am	Date and Hour of Discovery SAME
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	IF YES, To Whom? Solomon Hughes/Geoffrey Leking	
By Whom? David May	Date and Hour: 03/12/2014 8:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	IF YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* A corroded drain plug came out of the south water transfer pump resulting in a release. The MSO inserted a new plug and ordered stainless steel plugs for the pump.

Describe Area Affected and Cleanup Action Taken.\*

The affected caliche pad area was 80 ft. X 19 ft. and will be remediated according to NMOCD requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Spencer A. Cluff</i>	OIL CONSERVATION DIVISION	
Printed Name: Spencer Cluff	Approved by Environmental Specialist:	
Title: HSE Lead	Approval Date: 10-30-14	Expiration Date: 12-30-14
E-mail Address: spencer.a.cluff@conocophillips.com	Conditions of Approval: <i>Site inspection report submitted 8 minutes after as per NMOCD guidelines.</i>	Attached <input type="checkbox"/>  IRP - 3399
Date: 03/11/2014	Phone: 575-391-3143	

\* Attach Additional Sheets If Necessary

*Submit Final C-141 by  
12-30-14*

*09-24 217817  
N701430349896  
D701430350037*

OCT 30 2014