

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
NO Energy Minerals and Natural Resources
Oil Conservation Division
RECEIVED
100 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

| | | | |
|-----------------|---------------------------------------|---------------|-----------------|
| Name of Company | Oxy Permian Ltd. | Contact | Chancey Summers |
| Address | 1017 W. Stanolind Rd, Hobbs, NM 88240 | Telephone No. | (575) 397-8216 |
| Facility Name | State C Trac 11 Battery | Facility Type | Battery |
| Surface Owner | Mineral Owner | API No. | |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|----------------|
| | 2 | 21S | 36E | | | | | Lea County, NM |

Latitude _____ Longitude _____

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|---|------------------------|----------------------------|----------|
| Type of Release | Oil | Volume of Release | 150 bbls | Volume Recovered | 100 bbls |
| Source of Release | Hole in bottom of west oil tank | Date and Hour of Occurrence | 03/10/2014 | Date and Hour of Discovery | |
| Was Immediate Notice Given? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | Geoffrey Leking, NMOCD | | |
| By Whom? | Kathy Purvis, BBC International | Date and Hour | 03/11/2014 @ 9:20 am | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



A hole in the bottom of the west oil tank caused 150 bbls of oil to leak onto the ground. A vacuum truck recovered 100 bbls of oil and the tank was repaired.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 100' x 800' on location and off location. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

| | | |
|--|---|--------------------------|
| Signature:  | Approved by Environmental Specialist:  | |
| Printed Name: Chancey Summers | Approval Date: 11-10-14 | Expiration Date: 1-10-15 |
| Title: HES Specialist | Conditions of Approval: Sub Sample Required Duplicate & analyze in per NMOCD Smith - Silver Fuel C-141 b3 1-10-15 | |
| E-mail Address: Chancey.Summers@oxy.com | Attached <input type="checkbox"/> IRP-3417 | |
| Date: 3-12-14 Phone: (575) 397-8216 | | |

* Attach Additional Sheets If Necessary

NOV 14 2014

03/11/2014
670 143 455340
170 143 455585
P70 1431455865