

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT Form C-141
Revised August 8, 2011

NOV 26 2014
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1433051541		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P.		Contact: Tony Savoie			
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329			
Facility Name: Big Eddy Unit #158		Facility Type: Exploration and Production			
Surface Owner: Federal		Mineral Owner: Federal		API No. 30-015-35345	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	4	22S	28E	1830	South	1980	East	Eddy

Latitude N 32.420070 Longitude W 104.089737

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 5 bbls crude oil and 37 bbls produced water.	Volume Recovered: 3 bbls crude oil and 12 bbls produced water
Source of Release: Oil production Tank	Date and Hour of Occurrence: 11/24/14 time unknown	Date and Hour of Discovery: 11/24/14 at approximately 6:50 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson NMOCD	
By Whom? Amy Ruth	Date and Hour: 11/24/14 at 1:07 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A water dump valve failed sending all of the water to the oil tank causing it to overflow. The dump valve was replaced.

Describe Area Affected and Cleanup Action Taken.*
The spill impacted the entire surface of the dirt containment area of approximately 1500 sq. ft. the containment area is constructed with compacted caliche covered with pea gravel. All of the free standing fluid was recovered, due to the very hard coarse soil conditions the soil inside the containment, the impacted area is heavily saturated with produced water. Basin Environmental placed a one-call for the purpose of determining the vertical extent of contamination inside the bermed area. A summary report and remediation plan will be submitted after the sampling event scheduled for 12/1/14.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: <i>Mike Brannon</i>	
Title: Waste Management and Remediation Specialist		Approval Date: 11/26/14	Expiration Date:
E-mail Address: tasavoie@basspet.com		Conditions of Approval:	
Date: 11/25/14		Remediation per O.C.D. Rules & Guidelines	
Phone: 432-556-8730		SUBMIT REMEDIATION PROPOSAL NO	
		LATER THAN: 12/26/14	

* Attach Additional Sheets If Necessary

2RP-2031