

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

DEC 04 2014  
Submit to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB14338551015

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production	Contact	Rudy Zuniga, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575-390-5435
Facility Name	Sand 7 Fed 1	Facility Type	Oil

Surface Owner	Federal	Mineral Owner	Federal	API No.	30-015-25901
---------------	---------	---------------	---------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	7	18S	31E	1980'	FSL	2121'	FWL	Eddy

Latitude: 32.75989

Longitude: -103.90954

NATURE OF RELEASE

Type of Release Spill	Volume of Release 7bbls	Volume Recovered 2bbls
Source of Release hammer union on recirculation pump	Date and Hour of Occurrence December 3, 2014 10:30 AM	Date and Hour of Discovery December 3, 2014 10:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson, BLM & Mike Bratcher, OCD	
By Whom? Rudy Zuniga, Production Foreman	Date and Hour December 3, 2014 11:20 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.\* N/A

Describe Cause of Problem and Remedial Action Taken.\*

On December 3, 2014 at 10:30am Lease Operator was transferring oil with the recirculation pump at the Sand 7 Fed 1 when he discovered the hammer union leaking releasing 7bbls of oil in pasture. When Lease Operator discovered the leak he immediately shut down the recirculation pump and notified the Assistant Production Foreman.

Describe Area Affected and Cleanup Action Taken.\*

The area affected is approximately 2'x10' in the pasture area North of the Sand 7 Fed 1. Franco's Trucking was contacted and were able to recover 2bbls of oil from the spill by vac truck.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sheila Fisher	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Signed By Mike Bratcher	
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: Sheila.Fisher@dm.com	Approval Date: 12/4/14	Expiration Date: N/A
Date: Phone: 575.748.1829	Conditions of Approval:	Attached <input type="checkbox"/>
Remediation per O.C.D. Rules & Guidelines		

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 1/4/15

2RP-2642

\* Attach Additional Sheets If Necessary

**Bratcher, Mike, EMNRD**

---

**From:** Fisher, Sheila <Sheila.Fisher@dvn.com>  
**Sent:** Thursday, December 04, 2014 9:23 AM  
**To:** Sol Hughes (shughes@blm.gov); jlrobertson@blm.gov; Bratcher, Mike, EMNRD  
**Cc:** Jim Amos (jamos@blm.gov)  
**Subject:** Sand 7 Fed 1\_7bbls Oil Spill\_12.3.14  
**Attachments:** C-141\_Sand 7 Fed 1\_7bbls Oil Spill\_12.3.14.doc; Sand 7 Fed 1\_7bbls oil spill\_GIS Image\_12.3.14.Word.docx; Sand 7 Fed 1\_7bbls oil spill\_photo 1 of 4\_12.3.14.JPG; Sand 7 Fed 1\_7bbls oil spill\_photo 2 of 4\_12.3.14.JPG; Sand 7 Fed 1\_7bbls oil spill\_photo 3 of 4\_12.3.14.JPG; Sand 7 Fed 1\_7bbls oil spill\_photo 4 of 4\_12.3.14.JPG

Good Afternoon,

Attached please find the C-141, GIS Image and photos for the spill at the Sand 7 Fed 1. If you have any questions please feel free to contact me.

Thank you,

*Sheila Fisher*  
Field Admin Support  
Production

**Devon Energy Corporation**  
6488 Seven Rivers Hwy  
Artesia, NM 88210-9134  
575 748-1829 Direct  
[Sheila.Fisher@dvn.com](mailto:Sheila.Fisher@dvn.com)



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.

# ENVIRONMENTAL RELEASE NOTIFICATION

## Call-In Sheet

Date: 12/3/14

Notice received by: MB

Devon  
Name of Company/Phone #

Sand 7 Fed 1  
Facility Name

015-25901 7 18s 31e 12/3/14  
API # Sec. Township Range Date of Occurrence

12/3/14 7 AM Oil 7 bbls 2 bbls  
Date/Hour of Discovery Type of Release Volume of Release Volume Recovered

Briefly Describe Cause of Problem and action taken: Circ line failure - some of released fluid went into adjacent pasture

Rudy Zuniga w/ Devon 575-390-5435 12/3/14 11:10 AM  
Notice given by: Name/ Company Date/Hour Immediate Notice given

Date C-141 received: 12/4/14 2RP- 2642

\*\*\*\*\*

## FLARE NOTIFICATION

### Call-In Sheet

Date: \_\_\_\_\_

Notice received by: \_\_\_\_\_

\_\_\_\_\_  
Name of Company/Phone #

\_\_\_\_\_  
Facility Name

\_\_\_\_\_  
Date of Occurrence

\_\_\_\_\_  
Date/Hour of Flare

\_\_\_\_\_  
Type of Release

\_\_\_\_\_  
Flared MCF Volume

\_\_\_\_\_  
Volume Recovered

Briefly Describe Cause of Problem and action taken: \_\_\_\_\_

\_\_\_\_\_  
Notice given by: Name/ Company

\_\_\_\_\_  
Date/Hour Immediate Notice given

Date C-141 received: \_\_\_\_\_

2RP- \_\_\_\_\_