<ul> <li>811 S. First St., Artesia, NM 88210 <u>District II1</u></li> <li>1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u></li> <li>1220 S. St. Francis Dr., Santa Fe, NM 87505</li> </ul>	
	Re

.

### NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141 DEC 04 2014

Revised August 8, 2011

**Oil Conservation Division** 1220 South St. Francis Dr. Santa Fe, NM 87505

State of New Mexico

**Energy Minerals and Natural Resources** 

Submit 1 Copy to appropriate District Office in **RECEIVED** 

lease Notification and Corrective Action NABI433955644 Name of Company: COG Operating LLC **OPERATOR** Initial Report Final Report Name of Company: COG Operating LLC 229/37 Address: 600 West Illinois Avenue, Midland TX 79701 Contact: Robert McNeill Telephone No. 432-230-0077 Facility Name: SRO State Unit #18H Facility Type: Battery Surface Owner: State API No. 30-015-39999 Mineral Owner: State

# LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	17	26S	28E	330'	North	330'	East	Eddy

#### Latitude 32.0488883139878 Longitude -104.102110770708

#### **NATURE OF RELEASE**

Produced Water Source of Release:		Volume Recovered:
C CD I	55 bbls	50 bbls
	Date and Hour of Occurrence:	Date and Hour of Discovery:
Hole in fire tube	11/26/2014 1:30 pm	11/26/2014 1:30 pm
Was Immediate Notice Given? Xes In No Not Require	If YES, To Whom?	
By Whom? Lupe Carrasco	Date and Hour: 11/28/2014 7:53 a	am
Was a Watercourse Reached?	If YES, Volume Impacting the W	atercourse.
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* This release was caused by a hole in the fire tube of the heater treater. R standing fluid and dispose of at a NMOCD approved facility.	Repairs were made to the vessel. And v	vacuum trucks were dispatched to recover
Describe Area Affected and Cleanup Action Taken.* This release occurred within the lined bermed area. All fluids were able		
I hereby certify that the information given above is true and complete to regulations all operators are required to report and/or file certain release public health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remed or the environment. In addition, NMOCD acceptance of a C-141 report federal, state, or local laws and/or regulations.	e notifications and perform corrective a the NMOCD marked as "Final Report iate contamination that pose a threat to	actions for releases which may endanger " does not relieve the operator of liability ground water, surface water, human health
Signature:		RVATION DIVISION
Printed Name: Amanda Trujillo	Approved by Environmental Spectal	Sity / 40 Drennester
Title: Senior Environmental Coordinator	Approval Date: 2514	Expiration Date:
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached
	Demodiation and OOD 5	an & Cuidelinen
Date:     December 4, 2014     Phone: 575-748-6940       Attach Additional Sheets If Necessary	Remediation per O.C.D. Rul SUBMIT REMEDIATION PBO	

# Bratcher, Mike, EMNRD

From: Sent: To: Subject: Attachments: Amanda Trujillo <ATrujillo@concho.com> Thursday, December 04, 2014 2:35 PM Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD (C-141 Initial-Final) SRO State Unit #18H (30-015-39999) 11-26-2014 SRO State Unit #18H (TB) Initial-Final.pdf

Mr. Bratcher,

Attached is a C-141 for your consideration. The initial volume of 90 bbls was over estimated by field personnel in the initial report. The volume lost was 55 bbls. Please feel free to contact me if you have any questions or concerns.

Thank you,

## Amanda Trujillo

Senior Environmental Coordinator COG Operating LLC Cell: 505.350.1336 Office: 575.748.6930 <u>atrujillo@concho.com</u>

2407 Pecos Ave. Artesia, NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Lupe Carrasco Sent: Friday, November 28, 2014 7:53 AM To: <u>mike.bratcher@state.nm.us;</u> 'Heather.Patterson@state.nm.us' Subject: SRO State Unit #18H

Mr. Bratcher,

COG Operating LLC is reporting a release on the SRO State Unit #18H (30-015-39999). Section 17, Township 26S, Range 28E The release occurred at 1:30 PM on 11/26/14. Released: 90 bbls Produced Water Recovered: Pending

The release was due to a hole in the fire tube with all fluid contained within the lined facility. The site is being evaluated for clean-up and a C-141 will be submitted. If you have any additional questions please feel free to contact me.

Thanks!

Lupe Carrasco Environmental Coordinator Concho Resources Cell: <u>575.725.0787</u> Office: <u>575.748.6933</u> gcarrasco@concho.com

2208 W. Main St. Artesia , NM 88210

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.