

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS

State of New Mexico  
Energy Minerals and Natural Resources

HOBBS OGD

DEC 10 2014

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

RECEIVED

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Crockett State #2H	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. 30-025-41080
----------------------	----------------	----------------------

#### LOCATION OF RELEASE

Unit Letter H	Section 20	Township 21S	Range 33E	Feet from the 2310	North/South Line North	Feet from the 190	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.4652489180244 Longitude -103.586669949157

#### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 10 bbls PW	Volume Recovered: 9 bbls PW
Source of Release: Hole in fire tube	Date and Hour of Occurrence: 10:00am 11/27/2014	Date and Hour of Discovery: 10:00am 11/27/2014
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

This release was caused by a hole in the fire tube of the heater treater. Repairs to the equipment were made and vacuum trucks were dispatched to recover standing fluid and dispose of at an NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred within a lined facility. All fluids were able to be recovered and the facility put back into production.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 12-10-14	Expiration Date:
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: December 8, 2014 Phone: 575-748-6940		12P-3446

\* Attach Additional Sheets If Necessary

229132

DEC 11 2014

17019 3443 356  
17019 3443 3559