

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Lusk Deep Unit A #19	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-35244
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	17	19S	32E	660'	South	1650	West	Eddy <i>Lea</i>

Latitude 32.655021314435 Longitude -103.791580657662

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 20 bbls Oil; 400 bbls PW	Volume Recovered: 0 bbls Oil; 380 bbls PW
Source of Release: Fire	Date and Hour of Occurrence: 11/26/2014 2:50 pm	Date and Hour of Discovery: 11/26/2014 2:50 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Jim Amos - BLM	
By Whom? Lupe Carrasco	Date and Hour: 11/26/2014 10:07 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A fire occurred during a tank repair performed by a third party contractor. Two men of the contractor crew were injured and were transported to medical facilities. This incident is currently under investigation by COG and the contractor. The fire was extinguished by the fire department. Any standing fluids were recovered by vacuum trucks and dispose of at an NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.*

This spill remained mostly on the pad area however a 10' x 20' area of the pasture was impacted. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 12-10-14	Expiration Date: 2-10-15
E-mail Address: atrujillo@concho.com	Conditions of Approval: <i>Site specific report - Volume & number area upon NMOCD guidance.</i>	Attached <input type="checkbox"/> IRP-3447
Date: December 4, 2014 Phone: 575-748-6940	<i>Submit final C-141 by 2-10-15</i>	

* Attach Additional Sheets If Necessary

11/20/14 3443 6724
11/20/14 3443 6879

EC 11 2014