

**HOBBS OCD**

**DEC 11 2014**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**RECEIVED**

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: Gibson Energy		Contact: Bridget Sedlack	
Address: 3819 Towne Crossing, Ste 100 Mesquite, TX 75150		Telephone No.: 214-461-5563	
Facility Name: Iron House 19 State #1		Facility Type: CTB	
Surface Owner: State	Mineral Owner:	API No.: 30-025-40676	

**LOCATION OF RELEASE**

Unit Letter N	Section 19	Township 18S	Range 35E	Feet from the 200'	North/South Line South	Feet from the 1800'	East/West Line West	County: LEA
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	-------------

Latitude 32.7266 W Longitude -103.49970 W

**NATURE OF RELEASE**

Type of Release: OIL	Volume of Release: 19 bbls	Volume Recovered: 5 bbls
Source of Release: Overflow Transport Truck	Date and Hour of Occurrence: 11/9/2014; 4:00 pm	Date and Hour of Discovery: 11/9/2014 4:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Hobbs District I	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* The transport driver overflowed his truck while loading out oil causing a release of 19 barrels of oil. A vac truck responded same day and recovered 5 barrels of oil. Talon made an emergency One Call with NM 811 to start remedial activities.

Describe Area Affected and Cleanup Action Taken.\* The area affected from this release measured approximately 74-feet long by 40-feet wide. Talon mobilized personnel and equipment to the location and the visually impacted area was initially excavated between 0.5-feet to 2-feet deep where we encountered a rock shelf in the vicinity of sample location S-1 under the load-outs and towards the pump jack. Rock was also encountered in the vicinity of sample location S-2. The contaminated soil was transported to Len Land, LLC. Confirmation soil sampling was completed on 11/11/2014 and delivered to Cardinal Labs the same day for rush analysis. The lab results are attached along with a site map and groundwater data for the area. This battery has a high volume of truck traffic.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Bridget Sedlack	Approved by Environmental Specialist:	
Title: <i>Env't Manager - US Operations</i>	Approval Date: <i>12-11-14</i>	Expiration Date: <i>2-11-15</i>
E-mail Address: <i>bridget.sedlack@gibson.com</i>	Conditions of Approval: <i>Site specific report, Report &amp; monitor area as per NMOCD guidance Submit final C-141 by 2-11-15</i>	Attached <input type="checkbox"/>
Date: 11/13/2014 Phone: 214-461-5563	<i>IRP 7451</i> <i>6137</i>	

\* Attach Additional Sheets If Necessary

**DEC 12 2014**

*270143455 3064*  
*P 70193455 3315*