

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

DEC 10 2014

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1434455362

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: OXY USA Limited Partnership 142463	Contact: Chris Jones
Address: 102 S. Main St. Carlsbad, NM 88220	Telephone No.: 575-628-4121
Facility Name: Government AA #1	Facility Type: Well

Surface Owner: Federal	Mineral Owner:	API No.: 30-015-21286
-------------------------------	----------------	------------------------------

LOCATION OF RELEASE

Unit Letter C	Section 23	Township 20S	Range 28E	Feet from the 660'	North/South Line North	Feet from the 1980'	East/West Line West	County Eddy
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	-------------------------------	-------------------------------	-----------------------

Latitude **32.5645954 N** Longitude **-104.1504613 W**

NATURE OF RELEASE



Type of Release: Mixed Fluids oil & PW	Volume of Release: 5 bbls Oil & 10 bbls PW	Volume Recovered: 0 bbls
Source of Release: Stuffing Box	Date and Hour of Occurrence 11/17/2014	Date and Hour of Discovery 11/18/2014
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher & Heather Patterson @ NMOCD Jim Amos @ BLM	
By Whom? Kimberly Wilson	Date and Hour: 11/18/2014 1:45 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **The stuffing box blew out on the wellhead due to cold weather causing a release of 5 barrels of oil and 10 barrels of produced water. No fluids were recovered. Talon/LPE was contracted to perform an initial site assessment and soil sampling.**

Describe Area Affected and Cleanup Action Taken.*
The area affected is around the wellhead.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chris Jones	Approved by Environmental Specialist: 	
Title: HES Specialist	Approval Date: 12/10/14	Expiration Date: N/A
E-mail Address: Christopher.Jones@oxy.com	Conditions of Approval: <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: 11/19/2014 Phone: 575-628-4121	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 1/10/15

2RP-2652

Bratcher, Mike, EMNRD

From: Kimberly M. Wilson <kwilson@talonlpe.com>
Sent: Wednesday, December 10, 2014 1:29 PM
To: Bratcher, Mike, EMNRD; Jim Amos (jamos@blm.gov); Robertson, Jeffery
Subject: Oxy C-141's
Attachments: 20141210132015775.pdf; 20141210132002413.pdf

Please find attached the initial C-141's for the Government AA Fed #1 and the Martha Creek Gas Com Battery.

Thank you.

Kimberly M. Wilson

Project Manager
Talon/LPE
408 West Texas Avenue
Artesia, New Mexico 88210
Office: 575.746.8768
Fax: 575.746.8905
Cell: 575.602.3826
Emergency: 866.742.0742
Email: kwilson@talonlpe.com
Web: www.talonlpe.com



Better Business Bureau Torch Award for Marketplace Ethics: 2010 Winner, 2009 Finalist
Staples Foundation for Learning Hall of Fame Recipient: 2010
ICIC and Business Week- Top 100: 2010, 2009, 2008, 2007, 2006
Inc. 500/5000: 2012, 2011, 2010, 2009, 2008, 2007

Patterson, Heather, EMNRD

From: Kimberly M. Wilson <kwilson@talonlpe.com>
Sent: Tuesday, November 18, 2014 1:43 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; Jim Amos (jamos@blm.gov)
Cc: Christopher_Jones@oxy.com; David Adkins
Subject: Government AA #1 * 30-015-21286 * Lease No: NM-18293

On November 17, 2014 the stuffing box packing blew out on the wellhead due to the cold weather causing a release of 5 barrels of oil and 10 barrels of produced water at the above location. The release was contained on location.

Thank you.

Kimberly M. Wilson

Project Manager
Talon/LPE
408 West Texas Avenue
Artesia, New Mexico 88210
Office: 575.746.8768
Fax: 575.746.8905
Cell: 575.602.3826
Emergency: 866.742.0742
Email: kwilson@talonlpe.com
Web: www.talonlpe.com



Better Business Bureau Torch Award for Marketplace Ethics: 2010 Winner, 2009 Finalist
Staples Foundation for Learning Hall of Fame Recipient: 2010
ICIC and Business Week- Top 100: 2010, 2009, 2008, 2007, 2006
Inc. 500/5000: 2012, 2011, 2010, 2009, 2008, 2007