District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St: Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

DEC 16 20 Qil Conservation Division 1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

## Release Notification and Corrective Action

	OPERATOR	Initial Report
Name of Company Southern Union Gas Services, Ltd.	Contact	Crystal Callaway
Address 801 S. Loop 464, Monahans, TX, 79756	Telephone No.	(817) 302-9407
Facility Name: Trunk "O" 30" (RP-1020) Lea County Field Dept.	Facility Type	Natural Gas Gathering
Surface Owner State of New Mexico Mineral Owner: State of New Mexico Lease No.		
LOCATION OF RELEASE		
		/West Line   County
O 33 218 36E		Lea
Latitude N32 25.762 Longitude W103 16.212		
NATURE OF RELEASE		
Type of Release Crude Oil and Natural Gas	Volume of Release 33 mcf gas, 10 bbls oil	Volume Recovered 5 bbls
Source of Release Pipeline	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 8/21/06 Time: 12:02 p.m.
Was Immediate Notice Given? If YES, To Whom?		
☐ Yes ☒ No ☐Not Required		
By Whom? Tony Savoie, Southern Union Gas Services	Date and Hour:	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken: The 30" steel gathering pipeline, operating at 25 p.s.i. developed a leak, the line was excavated and the affected area was clamped at 3:46 p.m. on 8/21/06. All of the free standing fluid was removed with a vacuum truck. Clean soil was added to the impacted area to eliminate the risk to livestock and wildlife. Normal operating pressure on the line is 20 psi to 30 psi, with a potential H2S content of 4000 ppm. The affected section of pipeline has since been replaced.		
Describe Area Affected and Cleanup Action Taken. The affected area is pasture. An area covering approximately 700 sq. ft. was affected by the release and response activities.		
On or around August 30, 2006, remediation activities were conducted at the Trunk "O" 30" Release Site by an environmental contractor that is no longer affiliated with the site. On August 10, 2012, the site was revisited in an effort to determine if soil exhibiting benzene, BTEX, TPH and chloride concentrations above NMOCD regulatory standards remained in-situ and collect confirmation soil samples. Laboratory analytical reports from the confirmation soil samples suggested previous remediation activities met the requirements of the NMOCD.		
Please see the attached Basin Environmental Services Technologies Remediation Summary and Site Closure Request for details of remedial activities and the site investigation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
0.11/6.110	OIL CONSERVATION DIVISION	
Signature: Approved by District Supervisor:		
Printed Name: Crystal Callaway	Approved by San San	
Title: Crystal.Callaway@Regencygas.com	Approval Date: /2-/6-/9	Expiration Date:
E-mail Address: Crystal Callaway@Regencygas.com	Conditions of Approval:	
Date: 11/17/2014 Phone: (817) 302-9407		