

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
20 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

~~Release~~ Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: <b>ConocoPhillips</b>	Contact: <b>Jose A Zepeda</b>	
Address: <b>1410 N West County Road</b>	Telephone No. <b>575-391-3165</b>	
Facility Name: <b>State J2 Battery</b>	Facility Type: <b>Battery</b>	
Surface Owner: State	Mineral Owner: N/A	API No. <b>300250415700801</b>

LOCATION OF RELEASE

Unit Letter <b>T</b>	Section <b>2</b>	Township <b>20S 22S</b>	Range <b>36E 32E</b>	Feet from the	North/South Line	Feet from the	East/West Line	County <b>Lea</b>
-------------------------	---------------------	--------------------------------	-----------------------------	---------------	------------------	---------------	----------------	----------------------

**Latitude 32.4173 Longitude -107.2302**

NATURE OF RELEASE

Type of Release: <b>OIL/Produce Water</b>	Volume of Release: <b>15 BBLS</b>	Volume Recovered: <b>10BBL</b>
Source of Release: <b>Tank</b>	Date and Hour of Occurrence <b>12/17/2014 ~1730</b>	Date and Hour of Discovery <b>SAME</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Oberding, Tomas, VIA Email</b>	
By Whom? <b>Jose A Zepeda</b>	Date and Hour: <b>12/18/2014 ~1300</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\* On December 17, 2014 @ ~1730 hrs. MST @ the State J2 Battery, there was an accidental discharge from a tank over flow. COPC MSO received a call from supervisor about a stuffing box leak. COPC MSO arrived on location and discovered there was not a stuffing box leak; however a tank was running over. COCP MSO shut in location to cease anymore loss of fluid; he then checked panel views and head switches and all were incorrect. COPC MSO discovered transfer pump never came on to dump water from tank and MSO never received any alarms prior to this incident. COPC MSO got a vacuum truck to pull down tank he also contacted COPC I&E to come and get pump running. COPC MSO finally received alarms at approx. 7:30 P.M., about 2 hours after incident had already happened. Total loss of fluid was approx. 10bbbls oil and 5bbbls water. COPC MSO continued on without any further incidents. Spill site will be remediated in place in accordance with COPC and NMOCD guidelines.

Describe Area Affected and Cleanup Action Taken.\*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <b>JOSE A ZEPEDA</b>		OIL CONSERVATION DIVISION	
Printed Name: Jose A Zepeda		Approved by Environmental Specialist:	
Title: LEAD HSE		Approval Date: <b>12-18-14</b>	Expiration Date: <b>2-18-15</b>
E-mail Address: <b>Jose. A. Zepeda@conocophillips.com</b>		Conditions of Approval: <i>Site Supervisor required. Release not Remediate area as per NMOCD guidelines. Submit final C-141 by 2-18-15</i>	Attached <input type="checkbox"/> <b>IRP-3466</b>
Date: 12/18/14	Phone: 575-391-3158		

\* Attach Additional Sheets If Necessary

DEC 23 2014

5092  
12/19 3524974  
12/19 35249952