

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

Name of Company <i>Enterprise Field Services LLC</i>		Contact <i>Dina Babinski</i>
Address <i>PO Box 4324, Houston TX 77252</i>		Telephone No. <i>210-528-3824</i>
Facility Name <i>Pipeline ROW, A-3 Gathering Lateral</i>		Facility Type <i>Gas Gathering Pipeline</i>
Surface Owner <i>Private Owner</i>	Mineral Owner <i>NA - Pipeline</i>	API No. <i>NA</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>SESE</i>	<i>18</i>	<i>23S</i>	<i>28E</i>	<i>575</i>	<i>South</i>	<i>139</i>	<i>East</i>	<i>Eddy</i>

Latitude *N 32.29962* Longitude *W -104.11855*

NATURE OF RELEASE

Type of Release <i>Natural Gas</i>	Volume of Release <i>94 MCF</i>	Volume Recovered <i>NA</i>
Source of Release <i>Pipeline Leak and Blowdown</i>	Date and Hour of Occurrence <i>9/25/2014 @ 8:35 MDT</i>	Date and Hour of Discovery <i>9/25/2014 @ 8:35 MDT</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NM OIL CONSERVATION
ARTESIA DISTRICT
OCT 10 2014

Describe Cause of Problem and Remedial Action Taken.*



RECEIVED

Pipeline leak was detected by a driver passing by. The leaking portion was isolated, and pipeline section was blown down to carry out repair activities.

Describe Area Affected and Cleanup Action Taken.*

No liquid spills occurred requiring any cleanup actions.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: <i>Jon E. Fields</i>	Approved by: 	
Title: <i>Director, Field Environmental</i>	Approval Date: <i>10/10/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>jefields@eprod.com</i>	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: <i>10/7/2014</i>	Phone: <i>713-381-6684</i>	

* Attach Additional Sheets If Necessary

2RP-2624

AB1432857941
AB1432928304



Enterprise
Products

ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

October 3, 2014

NM OIL CONSERVATION
ARTESIA DISTRICT

OCT 10 2014

7014 1200 0001 0918 2611
Return Receipt Requested

RECEIVED

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report for Enterprise Field Services LLC
Releases on Carlsbad Area Gathering Lines**

Dear Mr. Bratcher:

Enclosed, please find the required C-141 Form for the pipeline leak and blowdown on our OBNOBO Line in Eddy County on September 25, 2014. The pipeline leak was detected by a driver passing by, and immediate repair activities were carried out to avoid further gas losses. This report is sent pursuant to NMAC 19.15.29 requirements for minor releases.

If you have any questions or need additional information, please contact Dina Babinski, our area Environmental Supervisor at 210-528-3824 or by email at djbabinski@eprod.com, or me directly at 713-318-6684.

Yours truly,

Jon E. Fields
Director-Field Environmental

/sjn