

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

FAB1435050051

Release Notification and Corrective Action

NA1435055401

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Enterprise Field Services LLC	Contact Dina Babinski
Address PO Box 4324, Houston TX 77252	Telephone No. 210-528-3824
Facility Name Pipeline ROW, A-3 Gathering Lateral	Facility Type Gas Gathering Pipeline
Surface Owner Private Owner	Mineral Owner NA - Pipeline
API No. NA	

LOCATION OF RELEASE

Unit Letter SWSE	Section 30	Township 22S	Range 27E	Feet from the 959	North/South Line South	Feet from the 95	East/West Line West	County Eddy
----------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	----------------------------	-------------------------------	-----------------------

Latitude **N 32.35828** Longitude **W -104.22909**

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 208 MCF	Volume Recovered NA
Source of Release Pipeline Leak and Blowdown	Date and Hour of Occurrence 9/6/2014 @ 16:45 MDT	Date and Hour of Discovery 9/6/2014 @ 17:15 MDT
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Pipeline leak was detected by the Carlsbad Police Department. The leaking portion was isolated, and pipeline section was blown down to carry out repair activities.

Describe Area Affected and Cleanup Action Taken.*

No liquid spills occurred requiring any cleanup actions.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ivan W. Zirbes	Approved by	Signed By 
Title: Sr. Director, Environmental	Approval Date: 12/22/14	Expiration Date: N/A
E-mail Address: snolan@eprod.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 9-9-2014	Phone: 713-381-6595	

* Attach Additional Sheets If Necessary

2RR-2680



ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

September 9, 2014

7013 2250 0002 3021 6271
Return Receipt Requested

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report for Enterprise Field Services LLC
Releases on Carlsbad Area Gathering Lines**

Dear Mr. Bratcher:

Enclosed, please find the required C-141 Form for the pipeline leak and blowdown on our Lateral A-3 Line in Eddy County on September 6, 2014. The pipeline leak was detected by the Carlsbad Police Department, and immediate repair activities were carried out to avoid further gas losses. This report is sent pursuant to NMAC 19.15.29 requirements for minor releases.

If you have any questions or need additional information, please contact Dina Babinski, our area Environmental Supervisor at 210-528-3824 or by email at djbabinski@eprod.com, or Jon Fields, Director-Field Environmental at 713-318-6684.

Yours truly,

Ivan W. Zirbes
Sr. Director, Environmental

/sjn
enclosure

RECEIVED

SEP 11 2014

ARTESIA DISTRICT

NM OIL CONSERVATION