

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

FEB 2 2015

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1503438578

Name of Company: BOPCO, L.P. <i>260737</i>		OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Contact: Tony Savoie
Facility Name: PLU-JV-CVX-Big Sinks #017H		Telephone No. 575-887-7329
AKA PLU Big Sinks 7-25-31 USA #1H		Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-40447

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	7	25S	31E	150	North	1980	West	Eddy

Latitude N 32.151139 Longitude W 103.818968

NATURE OF RELEASE

Type of Release: Crude Oil and produced water	Volume of Release: 320 bbls. crude oil and 82 bbls PW	Volume Recovered: 315 bbls crude oil and 78 bbls PW
Source of Release: Two Phase Separator	Date and Hour of Occurrence: 2/1/15 time unknown	Date and Hour of Discovery: 2/1/15 at approximately 9:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson, and Jim Amos "BLM"	
By Whom? Tony Savoie	Date and Hour: 11/18/14 at approximately 1:45 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A sight glass failed on the two phase separator, the sight glass was replaced.		
Describe Area Affected and Cleanup Action Taken.* The majority of the spill was contained in 0-Perm containment around the process equipment. Due to the pressure of the release approximately 7,225 sq.ft. of caliche pad area was impacted by the release. A vacuum truck recovered 312 bbls of oil and 78 bbls of water from the containment, and picked up 3 bbls of oil off the ground. The equipment was power washed. It was estimated that a total of 5 bbls oil and 4 bbls of water saturated into the soil. The spill areas will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>2/3/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval:	
Date: <i>2/2/15</i>	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO <i>31315</i>	
Phone: 432-556-8730	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

LATER THAN:

2RP-2781