

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company - Legacy Reserves Operating, LP	Contact
Address - PO box 10848, Midland, TX 79702-7848	Telephone No.
Facility Name - South Red Lake Unit 1	Facility Type

Surface Owner	Mineral Owner	Lease No. API # 30-015-00653
---------------	---------------	------------------------------

LOCATION OF RELEASE

Unit Letter C	Section 36	Township 17S	Range 27E	Feet from the 660'	North/South Line North	Feet from the 1650'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.796005 N Longitude -104.23543 W

NATURE OF RELEASE

Type of Release Mixed Fluids	Volume of Release 25 bbls	Volume Recovered 2 bbls
Source of Release Ruptured flow line	Date and Hour of Occurrence 2/8/11 am	Date and Hour of Discovery 2/8/11 pm
Was Immediate Notice Given? XX Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, NMOCD	
By Whom? Mike Stubblefield, Talon/LPE	Date and Hour 2/9/11 @15:05pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Frozen poly flow line ruptured. Line repaired the same day.

Describe Area Affected and Cleanup Action Taken.*

The affected area was downhill four hundred seventy feet (470') long by six feet (6') wide. Talon/LPE excavated the saturated soil from the impacted area to a depth of one and half feet (1.5') and transported to and NMOCD approved Solid Waste disposal facility. Talon/LPE backfilled the area with soil to match the surrounding terrain and the area seeded with an approved seed mixture.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: David J. Adkins	Approved by District Supervisor: 	
Title: District Manager Talon/LPE, Agent for Legacy Reserves	Approval Date: <u>1/30/15</u>	Expiration Date: <u>NA</u>
E-mail Address: dadkins@talonlpe.com	Conditions of Approval: <u>Final</u>	Attached <input type="checkbox"/>
Date: <u>5/23/11</u> Phone: <u>575-746-8768</u>		

* Attach Additional Sheets If Necessary

2RP-604