

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

FEB 12 2015

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1504355361 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC <u>229137</u>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: McIntyre A West 16	Facility Type: Well

Surface Owner: <u>Fed</u>	Mineral Owner:	API No. 30-015-31855
---------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	20	17S	30E	330	South	2160	East	Eddy

Latitude 32.8137613030574 Longitude -103.992641972529

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 5 bbls oil; 15 bbls PW	Volume Recovered: 3 bbls oil; 15 bbls PW
Source of Release: flowline	Date and Hour of Occurrence: 1/27/2015 10:00 am	Date and Hour of Discovery: 1/27/2015 10:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* This release was caused by a corrosion on a steel flowline. Vacuum trucks were dispatched to recover all standing fluid.		
Describe Area Affected and Cleanup Action Taken.* The impacted area in the pasture off the east side of the pad. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <u>A Trujillo</u>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <u>Hu</u>	
Title: Senior Environmental Coordinator	Approval Date: <u>2/12/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>atrujillo@concho.com</u>	Conditions of Approval: <u>Remediation per O.C.D. Rules &amp; Guidelines</u>	
Date: February 12, 2015 Phone: 575-748-6940	SUBMIT REMEDIATION PROPOSAL NO <u>3112115</u>	
* Attach Additional Sheets If Necessary		Attached <input type="checkbox"/>

Remediation per O.C.D. Rules & Guidelines  
SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 3/12/15

2RP-2809

## **Patterson, Heather, EMNRD**

---

**From:** Amanda Trujillo <ATrujillo@concho.com>  
**Sent:** Thursday, February 12, 2015 11:35 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Jeff Robertson (jlrobertson@blm.gov); Hughes, Solomon; james\_amos@blm.gov  
**Subject:** (Notification/C-141 Initial) McIntyre A West #16 (30-015-31855)  
**Attachments:** 1-27-2015 McIntyre A West 16 (FL) Initial.pdf

Mr. Bratcher/Mr. Robertson,

COG Operating LLC is reporting a release on the McIntyre A West #16 (30-015-31855)  
Unit O Section 20, Township 17S Range 30E  
The release occurred at 10:00 am on 1/27/2015  
Released: 5 bbls oil; 15 bbls PW  
Recovered: 3 bbls oil; 15 bbls PW

This release was caused by corrosion on a steel flowline. The impacted area in the pasture off the east side of the pad. Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

**Amanda Trujillo**  
Senior Environmental Coordinator  
COG Operating LLC  
Cell: 505.350.1336  
Office: 575.748.6930  
[atrujillo@concho.com](mailto:atrujillo@concho.com)

2208 W. Main St.  
Artesia, NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.