

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAR 03 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

NAB1506432906

303900

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Memorial Production Operating LLC	Contact	Heather Dolphin
Address	500 Dallas Street Houston TX 77002	Telephone No.	832-797-1334
Facility Name	NSLU-Grier Battery	Facility Type	Battery

Surface Owner	Mineral Owner	API No.
---------------	---------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	31	16S	31E					Eddy

Closest Well:

Latitude 32°52'47.49"N Longitude 103°54'39.84"W

North Square Lake Unit #125 API #30-015-04945

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	20bbbls	Volume Recovered	0bbbls
Source of Release	Buried Steel Injection Line at Battery	Date and Hour of Occurrence	8/3/14	Date and Hour of Discovery	0130hours
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Sol Hughes - BLM		
By Whom?	Heather Dolphin	Date and Hour	2/25/15		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	n/a		

If a Watercourse was Impacted, Describe Fully.*

n/a

Describe Cause of Problem and Remedial Action Taken.*

Summary of Incident: Main injection line leading west from battery blew a hole



Action: Shut in the line & repair.

Describe Area Affected and Cleanup Action Taken.*

Size affected (in Feet x Feet): 253' x 50' just outside of the fence around the battery

Summary of Clean-up: Request back hoe clean up waiting on approval cleanup method from BLM

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Heather Dolphin	Approved by Environmental Specialist: 	
Title: Sr. Regulatory Specialist	Approval Date: 3/5/15	Expiration Date: N/A
E-mail Address: heather.dolphin@memorialrd.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Revised 02/26/2015 Phone: 832-797-1334	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

REMIT REMEDIATION PROPOSAL NO
LATER THAN: 4/5/16

2RP-2851