

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAR 03 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1504435605		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company Devon Energy Production		Contact Rudy Zuniga			
Address PO Box 250		Telephone No. 575-390-5435			
Facility Name Antares 23 Fed #4H		Facility Type Oil			
Surface Owner Federal		Mineral Owner Federal		API No 30-015-41108	


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	23	19S	31E	2190	South	185	West	Eddy

Latitude: N 32°38'39.93"

Longitude: W 103°50'52.55"

NATURE OF RELEASE

Type of Release Spill Oil	Volume of Release .50 bbl	Volume Recovered 0 bbl
Source of Release .05 bbl of oil spilled through a lit flare	Date and Hour of Occurrence January 1, 2015 1:30 am	Date and Hour of Discovery January 1, 2015 1:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD Voicemail 575-234-6235 BLM Voicemail Jim Griswald	
By Whom? Jason Anderson	Date and Hour January 1, 2015 10:35 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* .50 bbl of oil spilled through a lit flare and the oil was burning on the trailer the flare was mounted on. The valve from upstream was closed immediately. Fire extinguishers were used to spray the fire and surrounding areas.		
Describe Area Affected and Cleanup Action Taken.*		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: Corina Moya	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 3/5/15	Expiration Date: N/A
E-mail Address: corina.moya@dmv.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 1-2-2015 Phone: 575-746-5559		

* Attach Additional Sheets If Necessary

2RP-2853