<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in

Form C-141

Revised August 8, 2011

Release Notification and Corrective Action										
		OPERATOR	☐ Initial Report							
Name of Company: BOPCO, L.P.	Contact: Tony Savoie									
Address: 522 W. Mermod, Suite 704 Carlsbad,	Telephone No. 575-887-7329									
Facility Name: Poker Lake Unit Battery #158		Facility Type: Exploration and Production								
Surface Owner: Federal	Mineral Owner	r: Federal	API No. 30-015-3	1690						

LOCATION OF RELEASE												
Unit Letter A	Section 7	Township 24S	Range 30E	Feet from the 660	North/ Nort	South Line h	Feet from the 660	East/West Line East		County: Eddy		
Latitude N 32.237400 Longitude W 103.914150												
NATURE OF RELEASE												
Type of Release: Produced water										Volume Recovered: 200 bbls		
Source of Release: Water transfer pump seal and piping failure.					3/21/11 Time unknown Time 7				and Hour of Discovery: 3/21/11 7:40 a.m.			
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required					equired	If YES, To Whom?						
	By Whom? Tony Savoie						Date and Hour: 3/21/11 at 8:20 a.m.					
Was a Watercourse Reached? ☐ Yes ☒ No					If YES, Volume Impacting the Watercourse.							
If a Watercou	irse was Im	nacted Descr	ihe Fully *			<u> </u>						
Describe Cause of Problem and Remedial Action Taken.* A water transfer pump seal and bearings failed causing excessive vibration on the discharge piping of the pump. The power was shut off and valves were												
Describe Area Affected and Cleanup Action Taken.* The entire area of the earthen containment was covered with produced water, approximately 4500 sq.ft. The free standing water was removed and the saturated area around the tanks and inside the containment was excavated and stockpiled on-site. Remediation activities were under way under an approved remediation plan. The caliche pad area measuring approximately 2000 sq.ft. was affected by the misting of the produced water being sprayed into the air.												
Reference 2RP-717 The release was remediated as per NMOCD approval. Please reference the attached Remediation Summary & Site Closure Request for remediation details. Day る Zova Zova												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
					OIL CONSERVATION DIVISION							
Signature: \ Qu \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \						,/ //						
Printed Name: Tony Savoie Approved by Environmental Specialist:								Vin				
Title: Waste	•		ation Spec	cialist	1	Approval Date: 3/2/15 Expiration Date: 1/1/A						
E-mail Addre	ess: tasavoid	e@basspet.com	n	-		Conditions of Approval:				Attached		
Date: 1/3/14	<u>-</u>	3/3/19		Phone: 432-556-	8730	Final Amarica !						

* Attach Additional Sheets If Necessary

2RP-717