<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

Name of Company COG Operating LLC

Address 550 W. Texas, Suite 1300 Midland, Texas 79701

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Initial Report** 

## **Release Notification and Corrective Action**

**OPERATOR** 

Contact Pat Ellis

Telephone No. (432) 230-0077

Facility Name Jenkins B Federal #/ Facility Type Well											
Surface Owner: Federal Mineral Ov			)wner	er			Lease No. (API#) 30-015-29451				
LOCATION OF RELEASE											
Unit Letter E	Unit Letter   Section   Township   Range   Feet from the   Nor						NORTH Feet from the 1090		Vest Line EST	County EDDY	
Latitude N 32.822824° Longitude W 103.999198°											
NATURE OF RELEASE											
Type of Relea	ase: Produc	ed Water			Volume of Release 100 bbls Volume Recovered 80 bbls						
Source of Release: Flowline						Date and Hour of Occurrence			Date and Hour of Discovery		
						02/05/2010 1:00p.m. 02/0				0 2:00p.m.	
Was Immedia	ate Notice C				If YES, To Whom?						
☐ Yes ☐ No ☐ Not Require											
					Mike BratcherOCD						
By Whom? Josh Russo Date and Hour 02/05/2010 2:30p.m.											
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.				
☐ Yes ☒ No							N/A				
If a Watercourse was Impacted, Describe Fully.*											
N/A											
N/A SCCEIVED											
TREU anti											
Describe Cause of Problem and Remedial Action Taken.*											
If a Watercourse was Impacted, Describe Fully.*  N/A  Describe Cause of Problem and Remedial Action Taken.*  There was a split in the flowline. The flowline has been repaired.  NMOCD ARTESIA											
Describe Area Affected and Cleanup Action Taken.*											
Tetra Tech inspected site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.											
										ant to NMOCD rules and	
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger											
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability											
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health											
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
rederar, state,	or iocariaw	s and/magai	ations.				OIL CONS	EDV/	TIONI	DIVISION	
OIL CONSERVATION DIVISION										7 V 13101V	
Signature: ///											
Driver d Nome	Ura Tayana	~ 11.	- Co 6	A	Approved by District Supervisor:						
Printed Name: Ike Tavarez Myent Fr COG										,	
Title: Project Manager						Approval Date: 3/13/15 Expiration Date: W/A					
E-mail Addres	s: Ike Tava	rez@TetraTeo	ch com	•		onditions of A	Annroval:			·	
Date: S	72-11	1		432) 682-4559			Topiovai.	n Thu	$\ell$	Attached	
Attach Additional Sheets If Necessary  212-390											
										UKY - 210	