District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

FUMW	1132	10513	38 ® ele	ase Notific	cation	and Co	rrective A	ction				
NAB15	0825	3811			OPERA	TOR		Initia	l Report	\boxtimes	Final Report	
		nterprise Fi	eld Servi	ces LLC	(Contact	Jim Heap			-		
PO Box 4324, Houston, TX 77252 Telephone No. 432-686-5404												
Facility Name Pipeline ROW, Mercury Fee Line Facility Type: Gas Gathering Pipeline												
Surface Owner Private-McDonald Mineral Owner							NA Lease No. NA					
				LOCA	ATION	OF RE	LEASE					
Unit Letter	Section	Township	Range	Feet from the	North/S	South Line	Feet from the	East/West Line		County		
	20	23S	28E							Eddy		
Latitude <u>32.290685 N</u> Longitude <u>-104.117925 W</u>												
NATURE OF RELEASE												
Type of Release Natural Gas and Pipeline Liquids Volume of Release 7,553 MCF Volume Recovered 0												
Source of Release Pipeline Leak							Date and Hour of Occurrence Date and Hour of Discovery					
			1	3 17:00 (MDT)			13 15:00 (N					
Was Immediate Notice Given? ☑ Yes ☐ No ☐ Not Required						If YES, To Whom? NMOCD Region 2, Mike Bratcher						
By Whom? Jim Heap						Date and Hour 17:00 CDT						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
								PECEIVED				
If a Watercourse was Impacted, Describe Fully.*									1	⊌l ⊟l∀		1
									۱۸	N 02 20)14	1
									J٢	14 02 -		ļ
								l	MO	CD ART	resi,	A
Describe Cause of Problem and Remedial Action Taken.* Suspected internal corrosion. The line was isolated, blown-down and scheduled for repair. Loss volume includes blow-down.												
Suspected	internal co	orrosion. The	line was i	solated, blown-de	own and	scheduled fo	or repair. Loss vo	lume include	s blow	v-down.		•
Describe Are	a Affected	and Cleanup	Action Tal	ken *			_					
					ated: land	downer will	be notified. Curr	ent observati	on she	ows a releas	e of lia	uids to the
surrounding	area. Repo	iir schedule is	not know	n at the time of	this repor	rt.						
I hamahar anat	:6. that tha	'			1 - 4 - 4 - 41	 		1 . 1.1		>5		
regulations a	iry that the	iniormation g are required t	iven above to report a	e is true and com nd/or file certain	piete to tr	ne best of my ofifications a	knowledge and	understand th	iat pur for rel	suant to INN leases which	HOCD I	rules and endanger
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability												
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
or the enviro	nment. In	addition, NMC ws and/or reg	OCD acce	ptance of a C-141	l report d	oes not relie	ve the operator of	responsibilit	y for c	compliance	with an	y other
icuciai, state	, or local la	Ms and/or reg	uiations.				OII CON	ICEDWAT	ION	DIVICE	ONI	
1.15/1						OIL CONSERVATION DIVISION						
Signature: I wilds						Approved by District Supervisor Miles Branches						
Printed Name: Jon E. Fields						Approved by	y District SdipePvi	go By Not	140	D.CARTER	250	-
Timed Name. John 2. Tiestas											11	
Title: Director, Field Environmental							Approval Date: 3/28/15 Expiration Date: N/					
E-mail Address: jefields@eprod.com							Conditions of Approval:					
			FINAL Attached									
		Phone: 71		95				11171				
* Attach Add	itional She	ets If Neces	sary							7	2RP	2909



December 30, 2013

Return Receipt Requested 7012 3460 0001 7236 3166

Mr. Mike Bratcher New Mexico Oil Conservation Division District 2 Office 811 South First Street Artesia, New Mexico 88210

RE: Form C-141 Report

Enterprise Field Services LLC

Mr. Bratcher

Enclosed, please find the requisite C-141 Forms for the following in Eddy County, New Mexico:

- Mercury Fee #1 on 9-6-2013
- Mercury Fee #2 on 9-6-2013
- Mercury Fee #3 on 10-4-2013
- Pennzoil A6 Lateral on 10-1-2013
- Quahada Ridge on 10-1-2013
- Trunk A on 9-1-2013
- White City Penn #4 on 10-11-13
- Line 1009 on 9-18-2013

If you have any questions or need more information, please contact Dina Babinski by phone at 210-528-3824, by email at <u>djbabinski@eprod.com</u> or me at 713-318-6595.

Regards,

Jon E. Fields

Director, Field Environmental

on Fulls

/bjm

attachments

