

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

0435
0AB1508257237

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Enterprise Field Services LLC	Contact	Jim Heap
	PO Box 4324, Houston, TX 77252	Telephone No.	432-686-5404
Facility Name	Pipeline ROW, Line A6	Facility Type:	Gas-gathering Pipeline
Surface Owner	BLM	Mineral Owner	NA
		Lease No.	NA

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	2	25S	26E					Eddy

Latitude: N 32.16419 Longitude: W -104.27445

NATURE OF RELEASE

Type of Release	Natural Gas	Volume of Release	425 MCF	Volume Recovered:	NatGas - 0
Source of Release	Suspected corrosion leak.	Date and Hour of Occurrence	12/20/2013 15:00-17:00 MST	Date and Hour of Discovery	12/20/2013 15:00 MST
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

JAN 09 2014

NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.*


Suspected corrosion leak. All gas was lost to atmosphere. BLM has been notified.

Describe Area Affected and Cleanup Action Taken.*

To be determined.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:



Printed Name: Jon E. Fields

Title: Director, Field Environmental

E-mail Address: jefields@eprod.com

Date: 1-6-2014 Phone: 713-381-6684

OIL CONSERVATION DIVISION

Approved by District Supervisor



Approval Date: 3/23/15

Expiration Date: N/A

Conditions of Approval:

FINAL

Attached ☐

* Attach Additional Sheets If Necessary


2RP-2911



ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

January 6, 2014



7012 3460 0003 3115 7742
Return Receipt Requested

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report for Enterprise Field Services LLC
Natural Gas Release on Carlsbad Gathering Lines**

Mr. Bratcher

Enclosed, please find the requisite FINAL C-141 Forms for the Baldrige Lateral Leak #2 (13DEC2013) and the Line A6 Leak #2 (20DEC2013) Repairs have been completed with no further reporting of liquids or gas-volume required.

This report is sent pursuant to 29 (19.15.29) NMAC and as follow-up to notifications made to your office. If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me directly at 713-318-6684.

Yours truly,

Jon E. Fields
Director, Field Environmental

/sjn
attachments