

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

FAB1508435844 Release Notification and Corrective Action

NAB1508439570

OPERATOR

Initial Report Final Report

Name of Company: Enterprise Products LLC	Contact: Jim Heap
Address: PO Box 4324, Houston, TX 77252	Telephone No.: 432-686-5404
Facility Name: Pipeline #1009	Facility Type: Pipeline

Surface Owner	Mineral Owner	API No.
---------------	---------------	---------

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	15	22S	31E					Eddy

Latitude: N32.393527 Longitude: W-103.770026

NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: 1.674 MMCF	Volume Recovered: 0
Source of Release: Blow-down for Maintenance - Relieve hydrate build-up.	Date and Hour of Occurrence: 12/21/2013 11:30 Start (MST)	Date and Hour of Discovery: 12/21/2013 13:30 End(MST)
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randy Dade (Region 2)	
By Whom? Jim Heap	Date and Hour: 11/21/2013 07:40 (MST)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*
CAUSE: Pipeline had to be blown down to relieve hydrate build-up.

Describe Area Affected and Cleanup Action Taken.*
All gas was lost to atmosphere.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Terry L. Hurlburt	Approved by Environmental Specialist:	
Title: Sr. Vice President	Approval Date: 3/25/15	Expiration Date: N/A
E-mail Address: snolan@eprod.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 12-23-2013 Phone: 713.381-6595		

* Attach Additional Sheets If Necessary


2RP 2016



ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

December 23, 2013



7012 3460 0003 3115 8978
Return Receipt Requested

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report for Enterprise Field Services LLC
Natural Gas Release on Carlsbad Gathering Lines**

Mr. Bratcher

Enclosed, please find the requisite FINAL C-141 Form for the Line 1009 blow-down in Eddy County to relieve hydrate build-up on 21DEC2013. There will be no excavation for repair on this blow-down

This report is sent pursuant to 29 (19.15.29) NMAC and as follow-up to a verbal notifications made to Randy Dade by phone on December 21, 2013. If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-318-6684

Regards,

Jon E. Fields
Director, Field Environmental

/sjn
attachments