<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
811 S. First St., Artesia, NM 88210
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Revised August 8, 2011

Form C-141

2RP-2928

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

FAB1	508	13584	₽Rele	ease Notific	eatio	n and Co	orrective A	ction						
nABI:			OPERATOR			☐ Initial Report ☒ Final Report								
Name of Co	mpany: E	Enterprise Pr	Contact: Jim Heap											
Address:		O Box 4324 ipeline #100	Telephone No.: 432-686-5404											
Facility Nar	ne: P	Facility Type: Pipeline												
Surface Ow	ner: S	API No.												
	•			LOCA	ATIO	N OF RE	LEASE							
Unit Letter	Section	Township	Range	Feet from the		h/South Line	Feet from the	East/W	est Line	County				
	8	218	35E								Edd	v [.]		
												<i>.</i>		
Latitude: <u>N 32.489693</u> Longitude: <u>W -103.384520</u>														
<u> </u>	NATURE OF RELEASE													
Type of Release: <i>Natural Gas</i> Source of Release:							Volume of Release: 902 Mscf Date and Hour of Occurrence:			Volume Recovered: 0 Date and Hour of Discovery:				
Pipeline Lea			01/11/20014 13:50 (MST)			01/11/2012 16:00 (MST)								
Was Immediate Notice Given?							If YES, To Whom?							
Yes No Not Required														
By Whom? Jim Heap Was a Watercourse Reached?							Date and Hour: 01/11/2014 17:00 (MST) If YES, Volume Impacting the Watercourse.							
Was a watercourse Reached? ☐ Yes ☒ No							1. 1.23, Forume impacting the Watercourse.							
If a Watercou	ırse was lm	pacted. Descr	ibe Fully.	*										
If a Watercourse was Impacted, Describe Fully.*														
RECEIVED														
										1				
Describe Cause of Problem and Remedial Action Taken.* CAUSE: Push-weld failure on over-pressure start-up.									JAN 2 1 2014					
					clamp) to be complet	ed on 15JAN201	4.	AIAAO)(J 4 D ==				
		•				,		<u> </u>	HAINIT	D ART	ESIA	<u> </u>		
Describe Area Affected and Cleanup Action Taken.* All gas was lost to atmosphere.														
Au gus wus i	osi io aimo	ърнеге.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and														
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability														
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other														
or the environ	nment. In a	ıddition, NMC Ws and/or regu	CD accep	tance of a C-141	report	does not reliev	e the operator of	responsil	oility for c	ompliance v	vith any	y other		
rederal, state,	Oriocaria	ws and/operegi	pations.	· · · · · · · · · · · · · · · · · · ·			OIL CON	SERV	ATION	DIVISIO	N			
							OIL CONSERVATION DIVISION							
Signature: fw / / wild						Approved by Environmental Specialist								
Printed Name: Jon E. Fields							Approved by Environmental Specialist:							
Title: Director – Field Environmental						Approval Date: 4115 Expiration Date: WA								
E-mail Addre	ess: jefield	ds@eprod.con	Conditions of Approval:											
Date: /-/(Phone: 713	4		FINAL				Attached	Auduleu []				
* Attach Addi				4			• • • • • • • • • • • • • • • • • • • •			<u></u>		0000	<u>_</u>	

January 16, 2014



7012 3460 0003 3115 7995 Return Receipt Requested

Mr. Mike Bratcher New Mexico Oil Conservation Division District 2 Office 811 South First Street Artesia, New Mexico 88210

RE:

Form C-141 Report for Enterprise Field Services LLC Natural Gas Release on Carlsbad Gathering Lines

Mr. Bratcher

Enclosed, please find the requisite Fnal C-141 Form for the Line 1009 release and blowdown in Eddy County. An initial investigation indicated that a "push-weld" in the line separated on start-up. Repair for this release will be completed on 15JAN2014.

This report is sent pursuant to 29 (19.15.29) NMAC and as follow-up to a verbal notification made to Randy Dade by phone on January 11, 2014. If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-381-6684

Regards,

Jon E. Fields

Director, Field Environmental

/sjn

attachments