

NM OIL CONSERVATION

ARTESIA DISTRICT

APR 17 2015

Form C-141

Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit to the appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1511042201

OPERATOR

☒ Initial Report ☒ Final Report

Name XTO ENERGY INC.	Contact Sherry Pack
Address 200 N. LORAIN, STE. 800	Telephone No. 432.620.6709
Facility Name Nash 42	Facility Type Battery

Surface Owner XTO ENERGY INC.	Mineral Owner XTO ENERGY INC.	API No. 30-015-21277
---	---	--------------------------------

LOCATION OF RELEASE

NASH 42 001

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	13	23S	29E	1980	N	660	E	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Flaring	Volume of Release 333 mcf	Volume Recovered
Source of Release casinghead gas	Date and Hour of Occurrence 4/16/15 6:00 am	Date and Hour of Discovery 4/16/15 3:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Heather Patterson	
By Whom? Patty Urias	Date and Hour 4/17/15 8:00	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully. *

Describe Cause of Problem and Remedial Action Taken. *

Enterprise Plant shutdown sending us to flare approx. 7000mcfd as of 6:00 am 4/16/15.

Describe Area Affected and Cleanup Action Taken. *

Flaring is being used to minimize emissions

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state or local laws and/or regulations.

Signature: <i>Patty Urias</i>	OIL CONSERVATION DIVISION	
Printed Name: Patty	Signed By: <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title: Regulatory Analyst	Approval Date: 4/20/15	Expiration Date: N/A
E-mail Address: patty_urias@xtoenergy.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 4/17/2015	Phone: 432.620.4318	

* Attach Additional Sheets If Necessary

2RP-2962

Patterson, Heather, EMNRD

From: Urias, Patty <Patty_Urias@xtoenergy.com>
Sent: Friday, April 17, 2015 8:28 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Midland Flare
Subject: Nash 42 Flare Notice
Attachments: doc01677520150417092431.pdf

Nash 42 Battery went to flare yesterday at 6AM due to Enterprise Plant shutdown. Please see attached documentation and thanks,

Patty Urias
Regulatory Analyst
XTO Energy Inc.
432.620.4318
432.618.3530 efax