

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	DWU Federal #1	Facility Type	Oil Well with Battery
Surface Owner	BLM	Mineral Owner	
		Lease No.	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	34	19S	28E					Eddy County, NM

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Oil and Produced water	Volume of Release	301 bbls	Volume Recovered	63 bbls
Source of Release	Nipple from the bottom of the tank	Date and Hour of Occurrence		Date and Hour of Discovery	1/08/2011 @ 12:00 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- NMOCD		
By Whom?	Kelton Beard	Date and Hour	see above		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Nipple coming off of the tank battery formed a leak. The well was shut in, tank taken out of service, and emptied. A vacuum truck was called to pick up the remaining fluid left on the ground.

Describe Area Affected and Cleanup Action Taken.\*

The area affected was inside the dikes around the tanks and approximately 60 feet into the pasture. Remediation was completed in accordance with approved plans from both the NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Christopher Jones		Approved by District Supervisor: 	
Title: HES Specialist		Approval Date: 4/21/15	Expiration Date: N/A
E-mail Address: Christopher.Jones@oxy.com		Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 3-4-13	Phone: (575) 628-4121		

\* Attach Additional Sheets If Necessary

22P-1402