District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brizzos Road, Aztec, NM 874.0 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

Cil Conservation Division 1220 South St. Francis Dr. Santa Fc, NM 87505 Form C-141 Revised March 17, 1999

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

	, ,, ===		Rel	ease	Notifi	catio	n and C	orrective A	etion						
OPERATOR Initial Report														Report	
Name of	Согарац	y Devon E	incry				Contact Tracy Kidd								
Address	P. O. Bo	x 250					Celephone No. 575-513-0628								
Artesia, NM 88211															
Facility Name: Snapping 10 Federal 1H							Facility Type Oil Wel.								
Surface Owner Mineral Ov							T		API #: 30-015-37899 2RP-1975						
					LOC	ATIO	OFRE	LEASE							
Uni: Letter	Section Township Range Feet from the 1			North/ North				est Line	County EDDY						
NATURE OF RELEASE															
Type o Rele							Volume of Kelease 10 bhis Volume Recovered -0 hola								
Source of Release: Poly line leak							Date and Hour of Discovery 9/29/13, 9/29/13, 3:00 AM 3:00 AM								
Was Immedia:e Notice Given? ☑ Yes ☐ No ☐ Not Require							If YES, To Whom? OCD/Mike Bratcher & BLM/Jeffery Robertson								
							Date and Heur: 10/1/.3, 8:45 AM								
By Whom* Aaron Kidd Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.								
☐ Yes ☑ No															
If a Watercou	irae waa linj	nacted, Descri	he Fu'ly.*	<u></u>											
N/A															
14727														!	
Describe Can	sc of Proble	m and Remed	lia Action	Taken	* 4 201	مرائيم امر	ted country	e calabase of 16 To	ovala of m	(12s.	L. N. 6.6			· ·	
Describe Cause of Problem and Remedia. Action Taken.* A poly line leaked causing a release of 16 barrels of mixed fluids. Fo fluids were recovered. The line was isolated, replaced and put back into service.														acu.	
Describe Area	Affected a	nd Cleanup A	et on Take	en * 1	Tulon T.PF	Was cor	tracted for th	e convention of th	is reletse	The in	pacted anea	from	this cele	กระ	
match the sur	d to a depth	of 2.5-feet do	op and ans	elytical Berone	testing wa	e comple	etec, The exc	cavation was back	a ot beiliñ:	rade usin	g new mat	criai, c	ontoure	d to	
I hereby certif	fy that the is	elemation Riv	ven above	is true :	and compl	cte to the	e best of my l	oowledge and ur	destand	that ourse	ent to NW	oco ·	rules sm	1	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuent to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger														,	
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability														у	
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD suspisses of a C-141 report does not relieve the operator of responsibility for compliance with any other														alth	
federal, state,	or local law	a and/or regal	ເຄດເຄາຍ.	M (16 307 1 22	Ma Carre	ashrud tara	es tiof testebe	tine obstance of to	eshouston	ny ter co	прилисе и	nn an	y otter	1	
Signature: Description Tool							OIL CONSERVATION DIVISION								
							Amazand by Olimba Canada and								
							Approved by District Supervisor:								
Title: Admin Field Support						A	Appenual Date/ 22/15 Expiration Date:								
Date: 3/3/2014 Phone: 375-748-9933							Conditions of Aperoval:						ן ד		

28P-1975