District 1 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

5844 Release Notification and Corrective Action **OPERATOR** Initial Report Final Report Name of Company: Enterprise Field Services LLC Contact: Jim Heap PO Box 4324, Houston, TX 77252 Telephone No.: 432-686-5404 Address: Facility Name: Pipeline #1009 Facility Type: **Pipeline** Mineral Owner API No. Surface Owner LOCATION OF RELEASE Range North/South Line Unit Letter Section Township Feet from the Feet from the East/West Line County 15 22S 31E Eddy Latitude: <u>N32.39359</u> Longitude: W-103.7009 NATURE OF RELEASE Type of Release: Natural Gas Volume of Release: 417 MCF Volume Recovered: 0 Source of Release: Date and Hour of Occurrence: Date and Hour of Discovery: Blow-down for Maintenance - Relieve hydrate build-up. 02/10/2014 11:00 Start (MST) 02/10/2014 12:30 End(MST) Was Immediate Notice Given? If YES, To Whom? ☐ Yes ☐ No ☒ Not Required By Whom? Date and Hour: Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* CAUSE: Pipeline had to be blown down to relieve hydrate build-up. NMOCD ARTESIA Describe Area Affected and Cleanup Action Taken.* All gas was lost to atmosphere. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Approved by Environment Section Printed Name: Jon E. Fields Title: Director - Field Environmental Approval Date: A **Expiration Date:** E-mail Address: jefields@eprod.com

Conditions of Approval:

Attach Additional Sheets If Necessary

Phone: 713.381-6684

Date: 2-14-14

1RP-2973

Attached



February 11, 2014

Return Receipt Requested 7012 3460 0000 1945 5504

. 0 . 4

NMOCD ARTESIA

Mr. Mike Bratcher New Mexico Oil Conservation Division District 2 Office 811 South First Street Artesia, New Mexico 88210

RE:

Form C-141 Report

Gas Loss Reported in the Carlsbad Gathering Field

Mr. Bratcher:

Pursuant to 29 (19.15.29) NMAC please find enclosed the requisite C-141 Form for the February 10, 2014 release from our Line 1009 in our Carlsbad Gathering Field, Eddy County. The release was made to relieve hydrate build-up in the line.

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-381-6684.

Regards,

Jon E. Fields

Director. Field Environmental

/sjn

attachments