

District I
1625-N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

APR 29 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1512150316

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: OXY USA INC	Contact: Chris Jones
Address: 102 S. Main St. Carlsbad, NM 88220	Telephone No.: 575-628-4121
Facility Name: Two Marks 36 State #4 SWD	Facility Type: SWD

Surface Owner: State	Mineral Owner:	API No.: 30-015-34833
----------------------	----------------	-----------------------

LOCATION OF RELEASE

Unit Letter O	Section 36	Township 21S	Range 24E	Feet from the 670'	North/South Line South	Feet from the 1905'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.430102 N Longitude -103.454029 W


NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 10 bbls	Volume Recovered: 0 bbls
Source of Release: 4" Steel Line Leak	Date and Hour of Occurrence 3/30/2015	Date and Hour of Discovery 3/30/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken: A 4" steel salt water disposal line caused a 10 barrel release on location due to stress on the line. All fluids stayed on location.

Describe Area Affected and Cleanup Action Taken.* ☐ The impacted area was on location only measuring approximately 60' x 80'. Talon/LPE was contracted to perform initial site assessment and soil sampling activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Chris Jones <small>Digitally signed by Chris Jones DN: cn=Chris Jones, o.ou, email=ckjones888@yahoo.com c=US Date: 2015.04.28 15:48:06 +05'00'</small>	OIL CONSERVATION DIVISION	
Printed Name: Chris Jones	Approved by Environmental Specialist: 	
Title: HES Specialist	Approval Date: 4/11/15	Expiration Date: N/A
E-mail Address: Christopher.Jones@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/28/2015	Phone: 575-628-4121	

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 4/11/15

* Attach Additional Sheets If Necessary

2RP-2977

Patterson, Heather, EMNRD

From: Kimberly M. Wilson <kwilson@talonlpe.com>
Sent: Wednesday, April 29, 2015 9:40 AM
To: Patterson, Heather, EMNRD; Bustamante, Amalia, EMNRD
Cc: Christopher_Jones@oxy.com; David Adkins
Subject: Oxy's Signed Initial C-141's
Attachments: Conoco 10 State #1 initial C-141.pdf; State 2 #3 CTB initial C-141.pdf; Two Marks 36 State 4 SWD C-141 initial.pdf

Good morning All,

Attached you will find a few signed initial C-141 for the above referenced release releases. My apologies for not getting some of these into you in a timely manner. I have had pneumonia for months. I had to be admitted to the ER. I should have everything caught up shortly, hopefully by the end of the week.

As you will see on the C-141's I will be drafting a work plan or have the location ready for further delineation.

Respectfully submitted,

Kimberly M. Wilson

Project Manager
Talon/LPE
408 West Texas Avenue
Artesia, New Mexico 88210
Office: 575.746.8768
Fax: 575.746.8905
Cell: 575.602.3826
Emergency: 866.742.0742
Email: kwilson@talonlpe.com
Web: www.talonlpe.com



Better Business Bureau Torch Award for Marketplace Ethics: 2010 Winner, 2009 Finalist
Staples Foundation for Learning Hall of Fame Recipient: 2010
ICIC and Business Week- Top 100: 2010, 2009, 2008, 2007, 2006
Inc. 500/5000: 2012, 2011, 2010, 2009, 2008, 2007