

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

ARTESIA DISTRICT

MAY 01 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141
Revised August 8, 2011

RECEIVED

Release Notification and Corrective Action

NAB1512434491

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Cypress 33 Federal #2H Battery	Facility Type	Battery

Surface Owner	BLM	Mineral Owner		API No.	30-015-37308
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	33	23S	29E					Eddy County, NM

Latitude N 32.26644° Longitude W 103.98343°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	12 bbls oil, 13 bbls produced water	Volume Recovered	0 bbls
Source of Release	Valve was left open causing the tank to spill over	Date and Hour of Occurrence	04/22/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD, James Amos-BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	04/28/2015 @ 9:41 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

A valve was left open causing the tank to spill 12 bbls of oil and 13 bbls of produced water onto the ground. No fluids were recovered and the valve was placed in the correct position.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 75' x 100' with the spill staying on location. Remediation will be completed in accordance with a remediation plan approved by both NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Chris Jones	Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=ckjones888@yahoo.com, c=US Date: 2015.04.30 12:57:45 -0500	OIL CONSERVATION DIVISION	
Printed Name: Christopher Jones	Approved by Environmental Specialist: 		
Title: HES Specialist	Approval Date: 5/4/15	Expiration Date: N/A	
E-mail Address: Christopher_Jones@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date:	Phone: (575) 628-4121	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 6/4/15**

2RP-2979

Patterson, Heather, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Friday, May 01, 2015 3:24 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; jamos@blm.gov
Cc: christopher_jones@oxy.com; cbrunson@bbcinternational.com;
kswinney@bbcinternational.com
Subject: Initial C-141, Cypress 33 Federal #2H Battery
Attachments: Initial C-141, Cypress 33 Federal #2H Battery.pdf

Attached is the initial C-141 for a leak that occurred at the Cypress 33 Federal #2H Battery on 04/22/2015 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.

1324 W. Marland

Hobbs, NM 88240

Phone: (575) 397-6388

Fax: (575) 397-0397

Email: kathy@bbcinternational.com