

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 <sup>TH</sup> Street	Telephone No. 575-748-1471	
Facility Name Robinson B Federal #1	API Number 30-015-03766	Facility Type Tank Battery
Surface Owner Federal	Mineral Owner Federal	Lease No. LC-064073

**LOCATION OF RELEASE**

Unit Letter F	Section 34	Township 17S	Range 29E	Feet from the 2310'	North/South Line North	Feet from the 2310'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.72166 Longitude 103.93253

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 18 B/PW	Volume Recovered 10 B/PW
Source of Release Gun Barrel Water Leg	Date and Hour of Occurrence 1/22/2010; PM	Date and Hour of Discovery 1/22/2010; PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Bobby Ballard/BLM Carlsbad	
By Whom? Greg Boans/Yates Drilling Company	Date and Hour 1/22/2010	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

**RECEIVED**  
 APR 25 2011  
 NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.\*  
Vacuum trucked recovered 10 bbls of produced water and hauled to disposal. Recovered contaminated soil (about 30 yds) hauled to Lea County Land Farm.

Describe Area Affected and Cleanup Action Taken.\*  
Repaired water leg. Removed recovered produced water and remediated contaminated soil to Lea Land Farm. Vertical/horizontal delineation sampling on 4/14/2011 analyzed for THP & BTEX (chlorides for documentation). **Depth to Ground Water: >100' (approximately 150', ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on amounts of produced water recovered, impacted soils excavated/hauled and analytical results, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Asher	Approved by District Supervisor: 	
Title: Environmental Regulatory Agent	Approval Date: <u>5/12/15</u>	Expiration Date: <u>NA</u>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: <u>Final</u>	Attached <input type="checkbox"/>
Date: Monday, April 25, 2011 Phone: 575-748-4217	2RP-	

\* Attach Additional Sheets If Necessary

2RP-650