

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action *Accepted as Initial*

NAB1515240134

OPERATOR

☒ Initial Report *ONLY* ☒ Final Report *HMP*

Name of Company Devon Energy Production <i>6137</i>	Contact Mike McMahan
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575.706.4165
Facility Name Dickens 29 Fed 3 Battery	Facility Type Oil

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-37220
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter H	Section 29	Township 16S	Range 28E	Feet from the 2310	North/South Line FNL	Feet from the 330	East/West Line FEL	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude: 32.89405

Longitude: 104.19059

NATURE OF RELEASE

Type of Release Spill Produced Water	Volume of Release 5 BBL	Volume Recovered 4 BBL
Source of Release Water haulers back valve	Date and Hour of Occurrence 2.18.15 at 12:45 PM	Date and Hour of Discovery 2.18.15 at 12:45 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM & OCD	
By Whom? Mike McMahan	Date and Hour 2.18.15 BLM at 6:05 PM / 2.18.15 OCD 6:10 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse ARTESIA DISTRICT MAY 13 2015	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.*

Driver was loading off of the produced water tank and did not realize the back valve on the trailer was opened.
The hauler shut off the pump and the open valve and called a supervisor.

RECEIVED

Describe Area Affected and Cleanup Action Taken.*

Fuson did one call and did cleanup work. They back dragged area where spray occurred on location. Roustabout rerouted line to prevent upward spray.

Analytical Data Required (HMP)

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeanette Barron</i>	OIL CONSERVATION DIVISION	
Printed Name: Jeanette Barron	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: <i>6/1/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>Jeanette.barron@dvn.com</i>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO. <i>2RP-3026</i>	
Date: 5.13.15 Phone: 575.748.1813	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

LATER THAN: *6/2/15*

Patterson, Heather, EMNRD

From: Patterson, Heather, EMNRD
Sent: Monday, June 01, 2015 6:44 AM
To: 'Barron, Jeanette'
Cc: 'McMahan, Mike'; 'Sanchez, Gilbert'; 'jamos@blm.gov'; Bratcher, Mike, EMNRD
Subject: RE: C-141 Dickens 29 Fed 3 Battery Final Report

Ms. Barron,

The OCD still has not received the initial C-141 for this incident. I will now alter the Final C-141 that you originally sent, and accept it as an INITIAL ONLY. A final C-141 will not be accepted without the proper closure documentation.

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Patterson, Heather, EMNRD
Sent: Thursday, May 14, 2015 9:08 AM
To: 'Barron, Jeanette'
Cc: McMahan, Mike; Sanchez, Gilbert; jamos@blm.gov; Bratcher, Mike, EMNRD
Subject: RE: C-141 Dickens 29 Fed 3 Battery Final Report

Ms. Barron,

Please submit an initial C-141 for this release, I do not see that the OCD ever got one. Also, a final C-141 should be accompanied with a closure report, complete with a site map, site ranking, and analytical data showing that remedial efforts were effective.

Thank you,

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Barron, Jeanette [<mailto:Jeanette.Barron@dvn.com>]
Sent: Wednesday, May 13, 2015 1:56 PM
To: jamos@blm.gov; Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: McMahan, Mike; Sanchez, Gilbert
Subject: C-141 Dickens 29 Fed 3 Battery Final Report

Please see attached. Should you have any questions please give me a call.

Thanks,

Jeanette Barron
Field Admin Support-Production

Devon Energy Corporation

P.O. Box 250

Artesia, NM 88211

575 748 1813 Direct

jeanette.barron@devn.com

devon

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.