

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Devon Energy Production	Contact	Rudy Zuniga, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575-390-5435
Facility Name	Aquila 22 Fed Com 1H	Facility Type	Oil

Surface Owner	Federal	Mineral Owner	Federal	API No.	30-015-40627
---------------	---------	---------------	---------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	22	19S	31E	990	FNL	50	FEL	Eddy

Latitude: 32.6505145262188

Longitude: -103.848726636463

NATURE OF RELEASE

Type of Release	Spill Produced Water	Volume of Release	10bbls	Volume Recovered	10bbls
Source of Release	3" fill line to produced water tank	Date and Hour of Occurrence	July 11, 2015 10:50 AM	Date and Hour of Discovery	July 11, 2015 10:50 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jim Amos, BLM		
By Whom?	Rudy Zuniga, Production Foreman	Date and Hour	July 11, 2015 12:30 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

NM OIL CONSERVATION
ARTESIA DISTRICT

JUN 15 2015


RECEIVED

If a Watercourse was Impacted, Describe Fully.*	N/A
---	-----

Describe Cause of Problem and Remedial Action Taken.*
On June 6, 2015 10:50 AM J&J Solutions Contractor called Asst. Foreman Automation who then contacted Asst. Production Foreman and reported a leak at the Aquila 22 Fed Com 1H, upon arrival it was discovered that a 3" fill line to the produced water tank had a hole in it releasing 9.5bbls produced water and .5bbl oil into lined containment. The affected tank was immediately switched out of and the line was isolated.

Describe Area Affected and Cleanup Action Taken.*
The affected area was a 30x80 area inside the lined containment. All fluids were recovered and containment has no holes. Containment and equipment will be pressure washed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sheila Fisher	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 6/16/15	Expiration Date: N/A
E-mail Address: Sheila.Fisher@dmv.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: June 15, 2015	Phone: 575.748.1829	

* Attach Additional Sheets If Necessary

2RP-3053

Patterson, Heather, EMNRD

From: Fisher, Sheila <Sheila.Fisher@dvn.com>
Sent: Tuesday, June 16, 2015 7:45 AM
To: Jim Amos (jamos@blm.gov); jlrobertson@blm.gov; Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Fulks, Brett
Subject: Aquila 22 Fed Com 1H_10bbls oil and produced water mix release_6.11.15
Attachments: C-141_Aquila 22 Fed Com 1H_10bbls oil and produced water mix release_6.11.15.doc; Aquila 22 Fed Com 1H_10bbls oil and produced water mix release_GIS Image_6.11.15 Word.docx; Aquila 22 Fed Com 1H_10bbls oil and produced water mix release_photo 2 of 4_6.11.15.JPG; Aquila 22 Fed Com 1H_10bbls oil and produced water mix release_photo 3 of 4_6.11.15.JPG; Aquila 22 Fed Com 1H_10bbls oil and produced water mix release_photo 4 of 4_6.11.15.JPG; Aquila 22 Fed Com 1H_10bbls oil and produced water mix release_photo 1 of 4_6.11.15.JPG

Categories: printed

Good Morning,

Attached please find the Initial and Final C-141, GIS Image and photos for the 10bbl oil & produced water mix release at the Aquila 22 Fed Com 1H.

If you have any questions please feel free to contact me.

Thank you,

Sheila Fisher
Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.