

07/04/2015 08:04

RECEIVED 07/06/2015 09:42
50574897205756279778
OCD ARTESIA

OFFICEMAX

PAGE 01/01

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

Oil Conservation Division

1220 South St. Francis Dr.

Santa Fe, NM 87505

JUL 13 2015

Submit 1 Copy to appropriate District Office in accordance with 19.13.29 NMAC.

RECEIVED

NAB1519053557 Release Notification and Corrective Action

ROGER SLAYTON DBA

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ESCUILLA OIL 228270	Contact	ERIC SANCHEZ
Address	PO Box 687	Telephone No.	505 840 4234
Facility Name	STANDARD STATE #2	Facility Type	Pump Jack

Surface Owner	State of NM	Mineral Owner	ROGER SLAYTON	API No.	30-005-10129
---------------	-------------	---------------	---------------	---------	--------------

STATE

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	5	8S	27E					Chaves

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Flow Line (Livestock)	Volume of Release	2 BBLs	Volume Recovered	2 BBLs excavated + recovered
Source of Release	Flow Line	Date and Hour of Occurrence	7-15	Date and Hour of Discovery	7-16-15
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?					
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Date and Hour			
		If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*
NONE


Describe Cause of Problem and Remedial Action Taken.*

Livestock Stepped on Flow Line

Describe Area Affected and Cleanup Action Taken.*

20' EAST of Pump Jack
2 BBLs oil Carried + spread by Rain Water on Oil Field Road
We have excavated to clean Soil, Contaminated Soil Stock Piled in Plastic, Hauled to proper Disposal site

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: ROGER SLAYTON	Accepted for record	
Title: Owner	Approved by Environmental Specialist: NMOC	Approval Date: 7/14/15
E-mail Address:	Expiration Date: N/A	Conditions of Approval:
Date: 7-10-15	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 8/16/15

2RP-3112