District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

2RP.3119

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action												
_nabl	5197	57320				OPERA	ГOR	Σ	Initia	ıl Report	Final Report	
Name of Company Oxy Permian Ltd. 1/0/09Lo						Contact CJ Summers						
		ive, Midland . 26 Federal	705		Telephone No. (432) 685-5824							
Facility Nat	ne rnk	. 20 recerai			Facility Type Battery							
Surface Owner BLM Mineral Owner							API No. 30-015-30412					
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the	North	/South Line	Feet from the	East/We	st Line	County		
M	26	238	30E				1			Eddy Coun	tv. NM	
				etitude N 22 2	70200	Lancitu	d. W 102 9590	100			.,,	
Latitude N 32.27028° Longitude W 103.85809°												
NATURE OF RELEASE												
Type of Release Produced water Source of Release Loadline valve left open							Volume of Release 18 bbls Volume Recovered 0 bbls Date and Hour of Occurrence Date and Hour of Discovery					
Godice of ite	TOUSC DO	idinio varvo ic		06/06/2015				overy				
Was Immediate Notice Given?							If YES, To Whom?					
Yes No Not Required												
By Whom? Kathy Purvis @ BBC International Inc. Was a Watercourse Reached?						Date and Hour 06/10/2015 @ 9:51 am If YES, Volume Impacting the Watercourse.						
☐ Yes ☒ No						If YES, Volume Impacting the Watercourse. NM OIL CONSERVATION ARTESIA DISTRICT						
If a Watercou	irse was Im	pacted, Descr	ibe Fully.	ŧ								
										J	儿 1 4 2015	
Describe Cause of Problem and Remedial Action Taken.*												
A loadline va	ilve was let	t open and lea	ked 18 bb	ls of produced wa	iter onto	the ground,	No fluids were re	covered ar	nd the va	lve was prope	erly closed.	
Describe Area Affected and Cleanup Action Taken.*												
The affected area is approximately 135' x 65' with most of the leak staying inside the lined battery on location. A small area measuring 6' x 75' leaked												
							on plan approved					
I houshy cost	fir that the	information of	tron chorse	is two and same	loto to t	ha haat af mir	knowledge and u	- James d	tlaat muuna	want to NMC	OCD rules and	
regulations al	ly mai me.	are required t	o report ar	id/or file certain r	elease n	ne best of my otifications a	ad perform correc	nderstand tive action	mat purs	eases which n	nay endanger	
public health	or the envi	ronment. The	acceptano	e of a C-141 repo	ort by th	e NMOCD m	arked as "Final R	eport" doe	s not reli	eve the opera	tor of liability	
should their o	perations h	ave failed to	idequately	investigate and r	emediat	e contaminati	on that pose a three e the operator of the operator operato	eat to grou	ind water	, surface wat	er, human health	
federal, state,				tance of a C-141	report d	ioes not renev	e the operator of i	responsibi	nty for c	ompuance wi	th any other	
The state of the s							OIL CONSERVATION DIVISION					
Signature:							//					
Digitature.		The second lives of the se	·			Approved by	Environmental S	necialist	/1		7	
Printed Name	: CJ Sun	nmers					Environmental p	pooning.	Mu	10		
Title: HES	Lead					Approval Dat	e: 7/16/18	5 Ex	piration	Date: NA		
E-mail Addre	ess: chane	cev summere	aoxy com			Conditions of	Annroval			Linco	_	
D-Man Addic	E-mail Address: chancey summers@oxy.com Date: 7-13-15 Phone: (432) 685-5824 Conditions of Approval: Remediation per O.C.D. Rules & Guidelineshed SUBMIT REMEDIATION PROPOSAL NO											
Date: 7	<u> - 1 5 · </u>	-13	Phone:	(432) 685-582	4	SUBMIT R	EMEDIATION	4 PROP	USAL			

Patterson, Heather, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>

Sent: Tuesday, July 14, 2015 12:45 PM

To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; jamos@blm.gov

Cc: C J Summers; Susan Miller; cbrunson@bbcinternational.com;

kswinney@bbc international.com; jgilkey@bbc international.com

Subject: Initial C-141, FNR 26 Federal #1 CTB, 6-6-15

Attachments: Initial C-141, FNR 26 Federal #1 CTB, 6-6-15.pdf

Attached is the initial C-141 for a leak that occurred at the FNR 26 Federal #1 CTB on 06/06/2015 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis
BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388

Phone: (575) 397-6388 Fax: (575) 397-0397

Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From:

Kathy Purvis <kathy@bbcinternational.com>

Sent:

Wednesday, June 10, 2015 9:51 AM

To:

Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; jamos@blm.gov

Cc:

C J Summers; Susan Miller; cbrunson@bbcinternational.com;

kswinney@bbcinternational.com; jqilkey@bbcinternational.com; Kathy Purvis

Subject:

FNR 26 Federal #1 CTB

This is to inform you that Oxy Permian had a leak at the FNR 26 Federal #1 CTB on June 6, 2015. Oxy spilled 18 bbls of produced water due to the loadline valve being left open. The preliminary report shows the leak measuring approximately 40' x 100' on location. No fluids were recovered. The release is located in the SW 4 of Section 26, T23S, R30E of Eddy County, NM. BBC International will remediate the location at a later date and an initial C-141 will follow. Driving directions: Between Carlsbad and Loving, turn east on NM31 and go 7 miles, turn right on NM128 (Jal Hwy) and go 7 miles, turn South on Mobley ranch Rd and go 5 miles, turn east and go 0.25 mile to location. API# 30-015-30412, GPS coordinates: N 32.27025° W 103.85793°

Kathy Purvis BBC International, Inc. 1324 W. Marland Hobbs, NM 88240 Phone: (575) 397-6388

Fax: (575) 397-0397

Email: kathy@bbcinternational.com