District I, 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised October 10, 2003
hmit 2 Copies to appropriate

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action	
0AB 1520 136984 154339 OPERATOR	
Name of Company SANdlutt Energy Contact Jackie Brewer	
Address P.O Box 711 Laurngton W.M. 882/0 Telephone No. 575-631-4592	
Facility Name Resler YARS # LON Flow I've Facility Type Flow live	
Surface Owner NMSLO Mineral Owner	Lease No. 30-015-02146
LOCATION OF RELEASE	
	N/South Line Feet from the East/West Line County
C 32 185 28E	Eddy
Latitude 32.708012Longitude 104.198542	
NATURE OF RELEASE	
Type of Release Oil From Flow live	Volume of Release 466/5 Volume Recovered
Source of Release leak in Flow live	Date and Hour of Occurrence Date and Hour of Discovery
Was Immediate Notice Given?	If YES, To Whom?
☐ Yes ☐ No 🗗 Not Required	
By Whom? Was a Watercourse Reached?	Date and Hour
Yes V No	If YES, Volume Impacting the Watercourse. NM OIL CONSERVATIO
If a Watercourse was Impacted, Describe Fully.*	ARTESIA DISTRICT
N/	JUL 1 4 2015
/A	302 14 2015
Describe Cause of Problem and Remedial Action Taken.* Leakin Flowing line less thew 5 bb15 RECEIVED	
Describe Area Affected and Cleanup Action Taken.* Dug oil Stained Soil out Dug down to 1/2 Ft, hauled 4 yards stained soil to R360 well replace with good Soil And till And resend area.	
Thereby certally that the information given above is true and complete to fife best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Signature: Signature: Printed Name: Dackie Brower	Approved by District Signed By Mile Brance
Title: Operator	Approval Date: 7/20/15 Expiration Date: NIA
E-mail Address: brewer 212 @ aol. com. Date: 7/13/2015 Phone: 575 631 4592 Attach Additional Sheets If Necessary	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 2020 200 200 200 320

Permian Basin, LLC Hobbs, New Mexico 88241-0388 • (575) 393-1079 • www.r360environmentalsolutions.com **NMOCD Order R9166** 3rd Party Ticket: Rig: Address Co Rep: Co Rep Phone # Company/Generator Lease Name Trucking Company Vehicle Number Driver (Print) Time Type of Material ☐ Soils ☐ Tank Bottoms ☐ Other Material (List Description Below) Receiving Area DESCRIPTION Bbls. Yard Gallons Volume of Material Call Out After Hours ☐ Debris Charge **GENERATOR CERTIFICATION STATEMENT OF WASTE STATUS** I hereby certify that according to the Resource Conservation and Recovery Act (RCRA) and the US Environmental Protection Agency's July 1988 regulatory determination, the above described waste is: (Check the appropriate classification) RCRA Exempt: Oil field wastes generated from oil and gas exploration and production operations and are not mixed with non-exempt waste.

RCRA Non-Exempt: Oil field waste which is non-hazardous that does not exceed the minimum standards for waste hazardous by characteristics established in RCRA regulations, 40 CFR 261.21-261.24, or listed hazardous waste as defined in 40 CFR, part 261, subpart D, as amended. The following documentation is attached to demonstrate the above-described waste is non-hazardous. (Check the appropriate

🖳 MSDS Information 🔲 RCRA Hazardous Waste Analysis 🔲 Process Knowledge 🔲 Other (Provide description above)

R360 Approval #

Agen

R360 Representative

(Signature

(Signature)

TANK BOTTOMS

Feet: Inches 1st Gauge

2nd Gauge Received BS&W/BBLS Received

Free Water

Total Received

White - R360

Canary - R360 Accounting

Pink - R360 Plant

BS&W

. 3.A