

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report  Final Report

Name of Company <i>St Mary Land &amp; Exploration Co.</i>	Contact <i>Tom Morrow</i>
Address <i>3300 N. A Street, Bldg. 7, Ste. 200, Midland, TX 79705</i>	Telephone No. <i>432-688-1773</i>
Facility Name <i>ESDU Injection Station</i>	Facility Type <i>Injection Station</i>
Surface Owner <i>BLM</i>	Mineral Owner <i>BLM</i>
Lease No.	

LOCATION OF RELEASE

Unit Letter <i>A</i>	Section <i>24</i>	Township <i>18S</i>	Range <i>31E</i>	Feet from the	North/South Line	Feet from the	East/West Line	County <i>Eddy</i>
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	-----------------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release <i>Produced Water</i>	Volume of Release <i>500 bbls</i>	Volume Recovered <i>410 bbls</i>
Source of Release <i>Fire destroyed water tanks &amp; gun barrel</i>	Date and Hour of Occurrence <i>7/16/08 6:00 AM</i>	Date and Hour of Discovery <i>7/16/08 6:00 AM</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Mike Bratcher w/NMOCD &amp; Jim Amos w/BLM</i>	
By Whom? <i>Bill Heame</i>	Date and Hour <i>5/30/2008 10:01 AM</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Cause: *Lightening struck injection station burning down (3) 500-bbl fiberglass suction tanks and scorching a 750 bbl fiberglass gun barrel. Fill lines were broken away from tanks causing the spill.*  
Remedial Action: *Notified all oil companies and shut-in all off lease water entering facility.*

Describe Area Affected and Cleanup Action Taken.\*

Affected Area: *85' x 45' = 3825 sq. ft. & 100' x 95' = 9500 sq. ft. Total = 13,325 sq. ft. (Pasture Land)*  
Cleanup Action: *Picked up standing fluid w/vacuum truck. Waiting on orders from BLM/OCD for further cleanup remediation action.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature <i>Dorria Huddleston</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <i>Dorria Huddleston</i>	Approved by District Supervisor: <i>[Signature]</i>	
Title: <i>Production Tech</i>	Approval Date: <i>7/20/08</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>dhuddleston@stmaryland.com</i>	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: <i>3/27/2009</i>	Phone: <i>432-688-1789</i>	

\* Attach Additional Sheets If Necessary

2RP-208