

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

# Release Notification and Corrective Action

NMLB 1520443233

155615 OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <u>Nadel &amp; Gussman Permian, LLC</u>	Contact <u>Kem McCreedy</u>
Address <u>601 N. Marientfeld Suite 508, Midland, TX 79701</u>	Telephone No. <u>432-682-4429</u>
Facility Name <u>Big Chief Fee No. 10</u>	Facility Type <u>Oil &amp; GAS</u>

Surface Owner <u>Buddy Adair</u>	Mineral Owner	Lease No.
----------------------------------	---------------	-----------

## LOCATION OF RELEASE API# 30-015-35337

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<u>D</u>	<u>22</u>	<u>22S</u>	<u>28E</u>					<u>Eddy</u>

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

## NATURE OF RELEASE

Type of Release <u>BRINE WATER</u>	Volume of Release <u>350-400 bbls</u>	Volume Recovered <u>40 bbls</u>
Source of Release <u>STEEL TANK ON LOCATION</u>	Date and Hour of Occurrence <u>4-2-07</u>	Date and Hour of Discovery <u>4-2-07</u>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>UNKNOWN but estimate 1000 hrs.</u>	
By Whom? <u>Cheryl Winkler</u>	Date and Hour <u>4-2-07</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <u>N/A</u>	

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

Spill occurred thru release from steel tank on location just prior to rig removal. Vac truck called and brine water was sucked up as much as possible

Describe Area Affected and Cleanup Action Taken.\*

Main area affected was pad and bar ditch along access road. Contaminated soil was picked up and placed in pit on location due to minor quantity.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Kem McCreedy</u> by <u>C. Winkler agent</u>	OIL CONSERVATION DIVISION	
Printed Name: <u>KEM MCCREEDY</u>	Approved by District Supervisor <u>TIM GUM</u> by <u>MB</u>	
Title: <u>Operations ENGINEER</u>	Approval Date: <u>4/2/07</u>	Expiration Date:
E-mail Address: <u>Kemm@naguss.com</u>	Conditions of Approval: <u>Remediation per NMOCD Rules &amp; Guidelines</u>	Attached <input type="checkbox"/>
Date: <u>4-12-07</u>	Phone: <u>432-682-4429 of project</u>	

\* Attach Additional Sheets If Necessary

2RP-3149