

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

AUG 7 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1522226346		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P. 2100737		Contact: Bradley Blevins		
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329		
Facility Name: PLU CVX JV BS 023H		Facility Type: Exploration and Production		
Surface Owner: State		Mineral Owner:	API No. 3001541392	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	2	25S	30E	50		1980		Eddy

Latitude: 32.152604 Longitude: 103.853799

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 198 barrels	Volume Recovered: 150 barrels
Source of Release: Frac tank overflowed	Date and Hour of Occurrence: 8-4-15	Date and Hour of Discovery: 8-4-15 @ 7:47am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - Jim Amos	
By Whom? Bradley Blevins	Date and Hour: 8-4-15 @ 11:50am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Well unloaded after well work was conducted causing the onsite frac tank to overflow to the ground surface.

Describe Area Affected and Cleanup Action Taken.*

Vacuum trucks were called to the location and recovered 150 barrels of oil

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bradley Blevins</u>		OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins		Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Assistant Remediation Foreman		Approval Date: <u>8/10/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: bblevins@basspet.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: <u>8-7-2015</u>	Phone: 432-214-3704	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 9/11/15

2RP-3192

Bratcher, Mike, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Friday, August 07, 2015 10:53 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Amos, James
Cc: Blevins, Bradley
Subject: Initial C-141 PLU CVX JV BS 023H
Attachments: doc04486320150807094354.pdf

All,

Please find the attached initial C-141 for the release that occurred at the PLU CVX JV BS 023H. If you have any questions or concerns please let me know.

Thank you,

Brad Blevins
Assistant Remediation Foreman
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com

Bratcher, Mike, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Tuesday, August 04, 2015 11:50 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Jim Amos
Cc: Blevins, Bradley
Subject: PLU CVX JV BS 023H
Attachments: photo 1.JPG; ATT00001.txt; photo 2.JPG; ATT00002.txt

All,

Bopco EHS was notified of a release at the PLU CVX JV BS 023H. The well unloaded and ran the frac tank over. Vacuum trucks were called to the location and were able to recover 150 barrels of oil. It is estimated that 40-50 barrels remain in the soil. I will follow up with an initial C-141, if you have any questions please let me know. Thanks