

NM OIL CONSERVATION

ARTESIA DISTRICT

AUG 24 2015

Form C-141

Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submit only to appropriate District Office in accordance with 19.15.29 NMAC.

FAB1432841543
NAB1523057915

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Enterprise Field Services LLC	Contact	Dina Ferguson
	PO Box 4324, Houston, TX 77210	Telephone No.	210-528-3824
Facility Name	Pipeline ROW, 30137 Gathering Lateral	Facility Type:	Gas Gathering Pipeline
Surface Owner	State of New Mexico	Mincral Owner	NA - Pipeline
		Lease No.	NA

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	13	19S	28E	72	South	394	West	Eddy

Latitude: N32.653899 Longitude: W-104.129186

NATURE OF RELEASE

Type of Release	Natural Gas	Volume of Release:	1,425 MCF	Volume Recovered:	N/A
Source of Release	Pipeline Blowdown	Date and Hour of Occurrence	08/12/2015 @ 10:00 MDT	Date and Hour of Discovery	08/12/2015 @ 8:00 MDT
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD District 2		
By Whom?	Osman De Leon	Date and Hour	08/12/2015 @ 8:00 MDT		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Pipeline blowdown was performed as part of the 30137 pipeline replacement project.					
Describe Area Affected and Cleanup Action Taken.*					
No liquid spill occurred as part of this event. No additional cleanup is necessary.					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:			
Printed Name:	Jon E. Fields		
Title:	Director, Field Environmental		
E-mail Address:	jefields@eprod.com		
Date:	8/24/2015	Phone:	713-381-6684
Approved by District Supervisor:		Signed By	
Approval Date:		8/24/15	
Expiration Date:		N/A	
Conditions of Approval:		FINAL	
Attached		<input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RD-3217

Bratcher, Mike, EMNRD

From: Nolan, Shiver <SNolan@eprod.com>
Sent: Monday, August 24, 2015 11:36 AM
To: Bratcher, Mike, EMNRD
Cc: Ferguson, Dina
Subject: 30137 Gathering Lateral
Attachments: Eddy County C-141 Initial - 30137 Gathering Lateral (8-12) August 2015.pdf

Attached is the initial C-141 for the 30137 Gathering Lateral Line.

Shiver J. Nolan
Sr. Compliance Administrator
Enterprise Products Operating LLC

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.