District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action											
NAB1516030165						OPERATOR					
						Contact Chancey Summers					
Address 6 Facility Nar		rive, Midiano tha Creek Ga				Telephone No. (432) 685-5824 Facility Type Gathering					
			is Com D								
Surface Ow	ner BL	M		Mineral Ov	vner	API No. 30-15-10323					
						OF RE					
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/West Line	County		
SE ¼	30	215	24E						Eddy County, NM		
Latitude N 32.44785° Longitude W 104.53339°											
NATURE OF RELEASE											
Type of Release Oil							Volume of Release 15 bbls Volume Recovered 0 bbls				
Source of Release Blowout of a gasket on the manway of the heater treater							Date and Hour of Occurrence Date and Hour of Discovery 05/26/2015				
Was Immediate Notice Given? ☐ Yes ☒ No ☐ Not Required						If YES, To Whom? Mike Bratcher, Heather Patterson- NMOCD; James Amos- BLM					
By Whom? Kathy Purvis, BBC International						Date and Hour 05/29/2015 @ 10:46am					
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse. NM OIL CONSERVATION					
☐ Yes ⊠ No									ARTESIA DISTRIC		
If a Watercou	rse was Im	pacted, Descr	ibe Fully.	•					JUN 9 2015		
30N 3 2015											
DECEN :											
Describe Cause of Problem and Remedial Action Taken.*											
A blowout of the gasket on the manway of the heater treater caused 15 bbls of oil to leak onto ground. No fluids were recovered and the gasket was replaced.											
Describe Area Affected and Cleanup Action Taken.*											
The affected area is approximately 200' x 250' on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.											
T1 1(')	C d d	· C 1	 -			1			IN LOCED		
regulations al	ty that the 1 I operators	intormation gi are required to	ven above o report ar	is true and comple d/or file certain rel	te to th ease no	ie best of my otifications ar	knowledge and u id nerform correc	nderstand that pur	suant to NMOCD rules and leases which may endanger		
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability											
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other											
federal, state,	or local lay	ws and/or regu	lations.	111100 01 11 C-1+1 10	port do	C3 HOT TOHEV	e the operator or	responsionity for t	compliance with any other	-	
						OIL CONSERVATION DIVISION					
Signature								i /			
Printed Name: Chancey Summers						Approved by Environmental Specialist:					
Finited Name	. Chance	y Summers					1101		111	=	
Title: HES Lead							e: [1] [9] 15	Expiration	Date: W/H		
							Conditions of Approval:				
Date: 6/	4/15		Rules & Guio	lelinės							
Attack Additional Charte of Management STERRIT REMINDING PROPOSAL WILL										1/1	
						ATER THA	N:	5	2RP.30A	め	

Patterson, Heather, EMNRD

From:

Kathy Purvis <kathy@bbcinternational.com>

Sent:

Monday, June 08, 2015 4:38 PM

To:

Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; jamos@blm.gov

Cc:

C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com;

jgilkey@bbcinternational.com

Subject:

Martha Creek Gas Com Battery

Attachments:

Initial C-141, Martha Creek Gas Com Battery.pdf

Attached is the initial C-141 for a leak that occurred at the Martha Creek Gas Com Battery on 05/26/2015 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis
BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388

Fax: (575) 397-0397

Email: kathy@bbcinternational.com

Patterson, Heather, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>

Sent: Friday, May 29, 2015 11:14 AM

To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; jamos@blm.gov

Cc: C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com;

jgilkey@bbcinternational.com

Subject: RE: Martha Creek Gas Com Battery

Please note: A correction needs to be made to the driving directions. The following directions are correct: North of Carlsbad at the intersection of Hwy 285 and NM 137, go WEST on NM 137 for 11.75 miles to Oxy Winston sign on right, turn right and go North 1.0 mile to the battery.

Kathy Purvis
BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397

Email: kathy@bbcinternational.com

From: Kathy Purvis [mailto:kathy@bbcinternational.com]

Sent: Friday, May 29, 2015 10:46 AM

To: mike.bratcher@state.nm.us; heather.patterson@state.nm.us; jamos@blm.gov

Cc: C J Summers (Chancey Summers@oxy.com); cbrunson@bbcinternational.com; kswinney@bbcinternational.com;

jgilkey@bbcinternational.com; Kathy Purvis (kathy@bbcinternational.com)

Subject: Martha Creek Gas Com Battery

This is to inform you that Oxy Permian had a leak at the Martha Creek Gas Com Battery on May 26, 2015. Oxy spilled 15 bbls of oil due to the blowout of a gasket on the manway of the heater treater. The preliminary report shows the leak measuring approximately 50' x 100' with some additional overspray both on and off location. No fluids were recovered. The release is located in the SE ¼, Section 30, T21S, R24E of Eddy County, NM. BBC International will remediate the location at a later date and an initial C-141 will follow. Driving directions: From Carlsbad, take the Queens Hwy East 20 miles to Oxy sign, turn right and go 1 mile South to the battery. API# 30-015-10323, GPS coordinates: N 32.44785° W 104.53339°

Kathy Purvis BBC International, Inc. 1324 W. Marland Hobbs, NM 88240

Phone: (575) 397-6388 Fax: (575) 397-0397

Email: kathy@bbcinternational.com