

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

#AB1523928857 Release Notification and Corrective Action

NAB1523929225

OPERATOR

☒ Initial Report ☒ Final Report

| | | |
|--|-------|----------------------------|
| Name of Company DCP MIDSTREAM | 36785 | Contact Nick Case |
| Address 2010 E Orchard Lane, Carlsbad NM 88220 | | Telephone No. 575-802-5225 |
| Facility Name BL-4-5 | | Facility Type pipeline |

| | | |
|------------------|---------------|-----------|
| Surface Owner NM | Mineral Owner | Lease No. |
|------------------|---------------|-----------|

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|

Latitude 32.21084 Longitude -103.59483

NATURE OF RELEASE

| | | |
|--|---|--|
| Type of Release Pipeline liquids/gathering system gas | Volume of Release <5bbl/118mcf | Volume Recovered |
| Source of Release: pipeline | Date and Hour of Occurrence 03/06/14 15:00 | Date and Hour of Discovery 03/06/14 15:00 |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Randy Dade | |
| By Whom? | Date and Hour 20:10 | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |


If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Inlet gathering pipeline leak. Remediate action is to remove and dispose of all affected soil and replace with new soil.

Describe Area Affected and Cleanup Action Taken.

Approximately 30x30 ft. of top soil. Cleanup will occur 03/07/14



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|---|--|-----------------------------------|
| Signature: | OIL CONSERVATION DIVISION | |
| Printed Name: Nicholas L. Case | Signed By: Approved by District Supervisor: | |
| Title: Environmental Specialist | Approval Date: 9/10/15 | Expiration Date: N/A |
| E-mail Address: nlcase@dcpmidstream.com | Conditions of Approval: FINAL | Attached <input type="checkbox"/> |
| Date: 03/10/14 | Phone: 575-802-5225 | |

* Attach Additional Sheets If Necessary

2RP-324B