

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 16 2015

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1526429388

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>16694</i>	Contact	Chancey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Neff Federal #1 and #3 SWD Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No. 30-015-28281	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	25	22S	31E					Eddy County, NM

Latitude N 32.36758° Longitude W 103.73418°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	Unknown, mixed with rain water	Volume Recovered	80 bbls, mostly rain water
Source of Release	Corrosion of a 4" discharge line	Date and Hour of Occurrence	08/24/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Heather Patterson, NMOCD and Shelly Tucker, BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	08/25/2015 @ 3:06 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Corrosion of a 4" steel discharge line caused an unknown amount of produced water to leak onto the ground. The line was repaired and a vacuum truck recovered 80 bbls of fluids, mostly rain water.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 80' x 75' just west of the lined battery. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Chancey Summers	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title:	HES Lead	Approval Date:	<i>9/21/15</i> Expiration Date: <i>N/A</i>
E-mail Address:	<i>Chancey.Summers@oxy.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	<i>9-11-15</i> Phone: (432) 685-5824	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: *10/22/15*

2RP-3268

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Wednesday, September 16, 2015 10:06 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Cc: C J Summers; 'Dusty Wilson'; cbrunson@bbcinternational.com;
kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141, Neff Federal #1 & #3 SWD Battery
Attachments: Initial C-141, Neff Fed #1 & #3 SWD Btry.pdf

Attached is the initial C-141 for a leak that occurred at the Neff Federal #1 & #3 SWD Battery on 08/24/2015 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Tuesday, August 25, 2015 3:06 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Cc: C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com; Kathy Purvis
Subject: Neff Federal #1 & #3 SWD Battery

This is to inform you that Oxy Permian had a leak at the Neff Federal #1 & #3 SWD Battery on August 24, 2015. Oxy spilled an unknown amount of produced water due to corrosion of a 4" steel discharge line. The amount is unknown because it is mixed with rain water. The preliminary report shows the leak measuring approximately 30' x 30' on location. A vacuum truck recovered approximately 80 bbls of fluids, including mostly rain water. The release is located in the northern half of Section 25, T22S, R31E of Eddy County, NM. BBC International will remediate the location at a later date and an initial C-141 will follow. Driving directions: From US 62/180, go South on C29 (Campbell Rd) for 14 miles to Mills Ranch Rd, turn left and go East 0.9 miles, turn left and go 0.2 mile to location.

API# 30-015-28281 GPS coordinates: N 32.367782° W 103.73385°

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com