application-pPACO607429642

District 1
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notificati	on and Co	rrective A	ction			-	
	OPERATOR			Initia	al Report	Final Report	
Name of Company Chevron USA Inc	Contact Larry Williams						
Address PO Box 1949 Eunice, NM 88231	Telephone No. 505-394-1237						
Facility Name L Van Etten 18	Facility Type Oil well						
Surface Owner S& W Cattle Company Mineral Owner	Private Lease No.859210						
	ON OF REI	EASE			RS 333	490000	
	rth/South Line		West Line County				
J 9 20 8 37E							
Latitude	Longitud	<del></del>	<u>,I</u>				
	E OF RELI		<del></del>				
Type of Release Oil and Produced water	Volume of Release 1 bbl oil and 4   Volume Recovered .5 bbl oil and 3.5 bbl						
	bbl water				water		
Source of Release Hole in 3" Poly flow line		Date and Hour of Occurrence 2/13/06 4:00 pm			Date and Hour of Discovery 2/13/06 2:15		
Was Immediate Notice Given?		If YES, To Whom?			<del>~</del>	- (	
X Yes No Not Required	d Pat Capetor	1					
By Whom? Larry Williams		Pat Capeton  Date and Hour2/14/06 1:00 pm  If YES, Volume Impacting the Watercourse.					
Was a Watercourse Reached?  Yes X No	If YES, Volume Impacting the Wat			urse.	\0\n^\cdot	Δ	
<u> </u>					/5	25	
If a Watercourse was Impacted, Describe Fully.*					78/	MAR 2006	
					20	Received	
					ব	Hobbs	
Describe Course Charles and Alberta Charles an			· · · · · · · · · · · · · · · · · · ·		/eg	OCD	
Describe Cause of Problem and Remedial Action Taken.*  Hot oiling poly flow line and a split came in line. Shut down hot oiler a	nd called out var	ruim truck			14		
to only poly now have use a spine cance in line. Only down not offer the	and carred out van	dum u dek.				\$2128293037	
						106 301	
Describe Area Affected and Cleanup Action Taken.*					<del></del>	The spenier	
10' x 20' area just outside of battery. Will remove hydrocarbon impacts	ed soil and take t	o land farm.					
						:	
I hereby certify that the information given above is true and complete to	o the hest of my l	cnowledge and u	inderstand t	at nuec	uant to NIMOC	D rules and	
regulations all operators are required to report and/or file certain release	notifications an	d perform correc	ctive actions	for rele	ases which ma	v endanger	
public health or the environment. The acceptance of a C-141 report by	the NMOCD ma	rked as "Final R	eport" does	not relie	eve the operato	r of liability	
should their operations have failed to adequately investigate and remedi or the environment. In addition, NMOCD acceptance of a C-141 report	iate contaminatio	n that pose a thr	eat to groun	d water,	, surface water,	human health	
federal, state, or local laws and/or regulations.	does not reneve	the operator of	responsibili	y for co	impliance with	any otner	
		OIL CONSERVATION DIVISION					
Signature: Command of the signature of t					22112221		
signature way wellow	1					:	
Printed Name: Larry Williams	Approved by I	District Supervise	or:		<del></del> -		
Title: HES Champion	Approval Date	·	Expiration Date:				
F-mail Address: law/@shawson cor-	Contidence of the continue of						
E-mail Address: lcwl@chevron.com	Conditions of			Attached [	] [		
D-4 0/34/06	I				I	1	
Date: 2/14/06 Phone:505-394-1237 Attach Additional Sheets If Necessary	<u></u>				1		