NM OIL CONSERVATION

ARTESIA DISTRICT

District I State of New Mexico
District II State of New Mexico
Energy Minerals and Natural Resources

OCT 0 2 2015

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr.

Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in RECE by Mance with 19.15.29 NMAC.

District II

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

+AB1527553369 Release Notification and Corrective Action												
n AB1527553523					OPERA	ГOR		✓ Initial	al Report	\boxtimes	Final Report	
						Contact Dina Ferguson						
PO Box 4324, Houston, TX 77210					Telephone No. 210-528-3824							
Facility Name Pipeline ROW, NZNNZF Line						Facility Type: Gas Gathering Pipeline						
Surface Owner State of New Mexico Mineral Owner					NA - Pipeline Lease No. NA							
LOCATION OF RELEASE												
1	ection Township	Range	Feet from the	North	/South Line	Feet from the		Vest Line	County			
G	G 36 20S 27E 49				North 515			West Eddy				
Latitude: <u>N 32.533395</u> Longitude: <u>W -104.233152</u>												
NATURE OF RELEASE												
Type of Release Natural Gas					Volume of Release: 735 MCF			Volume Recovered: N/A				
Source of Release Pipeline Leak.									Oute and Hour of Discovery 09/24/2015 @ 11:45 MDT			
Was Immediate Notice Given? ☑ Yes ☐ No ☐ Not Required					If YES, To Whom? NMOCD Reporting Hotline							
By Whom? Osman De Leon					Date and Hour 09/24/2015 @ 17:47 MDT							
Was a Watercourse Reached? ☐ Yes ☒ No					If YES, Volume Impacting the Watercourse.							
If a Watercourse was Impacted, Describe Fully.*												
Describe Cause of Problem and Remedial Action Taken.*												
Pipeline leak due to a broken fitting on pipeline tie in caused by a cow. Pipeline segment was clamped and blown down, and leaking portion was repaired.												
Describe Area Affected and Cleanup Action Taken.*												
No liquid spills occurred requiring any cleanup actions.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												

Signed By Approved by District Supervisor:

Approval Date:

Conditions of Approval:

* Attach Additional Sheets If Necessary

E-mail Address: jefields@eprod.com

Jon E. Fields

Signature:

Title:

Printed Name:

Date: 10-2-15

on & hilds

Director, Field Environmental

Phone: 713-381-6684

2RP-3312

Expiration Date:

Attached

Bratcher, Mike, EMNRD

From:

Mendez, Brenda <BJMendez@eprod.com>

Sent:

Friday, October 02, 2015 9:43 AM

To:

Bratcher, Mike, EMNRD

Cc:

Ferguson, Dina

Subject:

Eddy County NZNNZF Line (C-141 Form)

Attachments:

Eddy County C-141 Release Report NZNNZF Line (9-24) October 2015.pdf

Attached for your review and handling is the Release Notification & Corrective Action Form for the NZNNZF Line in Eddy County, NM.

Should you need additional information, please contact Ms. Dina Ferguson at 210-528-3824.

Thank you

Brenda J. Mendez - Planning and Reports Analyst

Enterprise Products Operating, LLC Tel (713) 381-8270 – Fax (713) 880-6660 bjmendez@eprod.com

This message (including any attachments) is confidential and intended for a specific individual and purpose. If you are not the intended recipient, please notify the sender immediately and delete this message.