

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

0AB1529340702

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company <i>Devon Energy Production</i>		Contact Daniel Suniga, Production Foreman	
Address <i>6488 Seven Rivers Hwy Artesia, NM 88220</i>		Telephone No. 575-390-5850	
Facility Name <i>Algerita 32 State Com I</i>		Facility Type <i>Oil</i>	
Surface Owner <i>State</i>	Mineral Owner <i>State</i>	API No. <i>30-015-35339</i>	

LOCATION OF RELEASE

Unit Letter M	Section 32	Township 22S	Range 26E	Feet from the 660	North/South Line FSL	Feet from the 1160	East/West Line FWL	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude: 32.34283 Longitude: -104.32000

NATURE OF RELEASE

Type of Release Oil & PW release	Volume of Release 10bbl <i>8bbl PW/2bbl oil</i>	Volume Recovered 7bbls <i>6bbl PW/1bbl oil</i>
Source of Release 30 pound gauge	Date and Hour of Occurrence October 3, 2015 11:30 AM	Date and Hour of Discovery October 3, 2015 11:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, OCD	
By Whom? Mike McMahan, Asst. Production Foreman	Date and Hour October 3, 2015 11:40 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

NM OIL CONSERVATION
ARTESIA DISTRICT
OCT 19 2015
RECEIVED

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
The 3-phase separator lost gas psi causing it not to dump properly which over pressured a 30# gauge that broke and released approximately 8bbl produced water and 2bbl oil out the gauge. The well was immediately shut in and a dike was built to stop the fluid from running off location.

Describe Area Affected and Cleanup Action Taken.*
Approximately 8bbl of mixed fluid stayed inside containment and approximately 2bbl mixed fluid went into pasture due to a hole in the containment. A vac truck was contacted to start recovering fluid and 7bbl mixed fluid was recovered. An environmental agency will be contacted for the clean-up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Sheila Fisher</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <i>Field Admin Support</i>	Approval Date: <i>10/20/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>Sheila.Fisher@dvn.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>10/16/15</i> Phone: <i>575.748.1829</i>	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 11/20/15 *2RP-3345*

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Fisher, Sheila <Sheila.Fisher@dvn.com>
Sent: Monday, October 19, 2015 8:31 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Shelly Tucker (stucker@blm.gov); Jim Amos (jamos@blm.gov)
Cc: Fulks, Brett; Harris, Jacqui; Teel, Veronica; Barron, Jeanette
Subject: RE: Algerita 32 State 1_10bbl mixed oil & PW release_10.3.15
Attachments: Algerita 32 State 1_10bbl mixed oil & PW release_10.3.15_Initial C-141.doc; Algerita 32 State 1_10bbl mixed oil & PW release_10.3.15_GIS Image Word.docx; Algerita 32 State 1_10bbl mixed oil & PW release_10.3.15_photo 1 of 2.jpg; Algerita 32 State 1_10bbl mixed oil & PW release_10.3.15_photo 2 of 2.jpg

Good Morning,

Let me know if you can open them this time?

Thank you,

Sheila Fisher
Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]
Sent: Monday, October 19, 2015 8:21 AM
To: Fisher, Sheila <Sheila.Fisher@dvn.com>; Patterson, Heather, EMNRD <Heather.Patterson@state.nm.us>; Shelly Tucker (stucker@blm.gov) <stucker@blm.gov>; Jim Amos (jamos@blm.gov) <jamos@blm.gov>
Cc: Fulks, Brett <Brett.Fulks@dvn.com>; Harris, Jacqui <Jacqui.Harris@dvn.com>; Teel, Veronica <Veronica.Teel@dvn.com>; Barron, Jeanette <Jeanette.Barron@dvn.com>
Subject: RE: Algerita 32 State 1_10bbl mixed oil & PW release_10.3.15

Shelia,

We have not been able to open the C-141. Could you please check and resend? The C-141 is listed as the GIS image.

Thanks,

Mike Bratcher
NMOCD District 2
811 S. First Street
Artesia, NM 88210

O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

From: Fisher, Sheila [<mailto:Sheila.Fisher@dvn.com>]
Sent: Friday, October 16, 2015 3:20 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Shelly Tucker (stucker@blm.gov); Jim Amos (jamos@blm.gov)
Cc: Fulks, Brett; Harris, Jacqui; Teel, Veronica; Barron, Jeanette
Subject: Algerita 32 State 1_10bbl mixed oil & PW release_10.3.15

Good Afternoon,

Attached please find the Initial C-141, GIS Image and photos for the 10bbl oil & produced water release at the Algerita 32 State 1.

If you have any questions please feel free to contact me.

Thank you,

Sheila Fisher
Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.